



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBW 944G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOTLID (CONSISTENT)	BENT	879.60	879.60
1	REAR BUMPER (CONSISTENT)	CRACKED	612.90	612.90
1	REAR BUMPER BEAM (CONSISTENT)	SERVICEABLE	156.00	-
1	REAR END PANEL (CONSISTENT)	BENT	680.90	680.90
1	REAR BOOTLID LOCK (CONSISTENT)	BENT	111.90	111.90
2	REAR BOOTLID HINGES @\$78.90 (CONSISTENT)	SERVICEABLE	157.80	-
1	REAR BOOTLID WEATHERSTRIP (CONSISTENT)	NECESSARY	194.90	194.90
2	REAR TAILLAMPS @\$419.60 (CONSISTENT)	CRACKED	839.20	839.20
2	REAR BOOTLID LAMPS @\$282.95 (CONSISTENT)	SERVICEABLE	565.90	-
1	REAR BOOTLID LOGO (CONSISTENT)	NECESSARY	50.70	50.70
1	REAR BOOTLID 'COROLLA' EMBLEM (CONSISTENT)	NECESSARY	49.50	49.50
1	REAR BOOTLID 'ALTIS' EMBLEM (CONSISTENT)	NECESSARY	49.50	49.50
1	REAR BOOTLID '1.6' EMBLEM (CONSISTENT)	NECESSARY	36.90	36.90
2	REAR BUMPER BRACKET @\$92.60 (CONSISTENT)	CRACKED	185.20	185.20
1	REAR BUMPER SPONGE (CONSISTENT)	CRACKED	142.65	142.65
1	REAR END PANEL GARNISH (CONSISTENT)	CRACKED	209.65	209.65
1	REAR BOOTLID CHROME (CONSISTENT)	SERVICEABLE	159.15	-
2	REAR BUMPER RETAINERS @\$85.90 (CONSISTENT)	SERVICEABLE	171.80	-
1	REAR BOOTLID LOCK CATCH (CONSISTENT)	BENT	56.95	56.95
2	REAR BUMPER REFLECTOR @\$69.80 (CONSISTENT)	SERVICEABLE	139.60	-
1	SET REAR REVERSE SENSOR	SERVICEABLE	-	-
1	REAR NUMBER PLATE	SERVICEABLE	50.00	-
	LESS 25% DISCOUNT		-	-1,025.11
			5,500.70	3,075.34
	<u>LABOUR</u>			
	TO CHECK WIRING .		50.00	30.00
	TO REMOVE AND REFIX REAR REVERSE SENSOR .		150.00	60.00
	PANEL BEATING.		1,000.00	700.00
	TO SPRAY PAINTING .		1,200.00	600.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO UNDERSEAL .		150.00	60.00
			2,550.00	1,450.00
GRAND TOTAL			8,050.70	4,525.34
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,600.00

Report Ref No. CC4/ASM21000361/R1ga3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.