

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG21000363/T1QD3E2

**Date:** 09/02/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700070944  
Claimant Vehicle No : SMJ9637Y Insured Vehicle No : SJM999G  
Date of Loss: 04/01/2021 Nature of Claim: TP Claim No: 5162479202SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMJ9637Y**  
Make & Model: TOYOTA VELLFIRE, 2.5 Z G CVT (A) Engine No: 2ARJ228306  
Reg. Date: 26/03/2019 (Man. Year: 2018) Chassis No: AGH300221317  
Colour: Black Odometer: 71773 km  
Engine Capacity: 2493 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 245/40 R20 Rear Tyre Size: 245/40 R20  
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm  
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 07/01/2021  
Date Inspected: 11/01/2021 Inspected At: Mw Brothers Auto Repair (kaki Bukit) (HQ)  
2 KAKI BUKIT AVENUE 2, #02-02 KAKI BUKIT  
AUTOHUB  
Singapore 417921  
Estimated Period of Repair: 3.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT LH DOOR	Bent	0.00 F	*- F
2	1		*FRT LH DOOR PROTECTOR	Cut	0.00 F	*- F
3	1		*FRT LH DOOR CHROME MOULDING	Cut	0.00 F	*- F
4	1		*FRT LH DOOR GLASS REGULATOR	* Check	0.00 F	*- F
5	1		*FRT LH DOOR LOCK	* Check	0.00 F	*- F
F=Franchise part.						
Total Parts (\$\$)					0.00	0.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >