



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2105631

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 11/08/2021
Reference CC6/CTI21000364/Uea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. GBK 3922M
Insured Veh. SMM 9463R
Claim No. SNM21D200307
Policy No. DMHCSNA00001932000
Accident Date 07/01/2021
Inspection Date 08/01/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Ref: CC6/CTI21000364/Uea3q2	
			Date: 11/08/2021	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMM 9463R	Veh. Inspected	GBK 3922M	
Policy No.	DMHCSNA00001932000	Coverage (\$)	0.00	
Claim No.	SNM21D200307	Excess (\$)	0.00	
Assign From		Assign Date	08/01/2021	
2. Vehicle Particulars & Condition				
Make & Model	CITROEN BERLINGO (M)	c.c	1499	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	VR7EFYHYCKJ722867	Colour	WHITE	
Odometer	19666 KM	Steering	AFFECTED	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	MICHELIN	8 mm	
L/H Front Tyre	205/60 R16	MICHELIN	8 mm	
R/H Rear Tyre	205/60 R16	MICHELIN	8 mm	
L/H Rear Tyre	205/60 R16	MICHELIN	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/01/2021	Inspection Date	08/01/2021	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBK 3922M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER TOP	DEEP CUT / TORN	1,550.00	517.00
1	FRONT BUMPER BOTTOM BLACK	DISTORTED	1,200.00	602.00
1	FRONT BUMPER FOG LAMP O/S	CRACKED	650.00	450.00
1	FRONT BUMPER FOG LAMP GARNISH O/S	MISSING	420.00	222.00
1	FRONT BUMPER FOG LAMP INNER BRACKET O/S	CRACKED	355.00	205.00
1	FRONT BUMPER SIDE RETAINER O/S	NOT NECESSARY	68.00	-
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	45.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	685.00	-
1	FRONT BUMPER SPONGE	TORN	320.00	105.00
1	FRONT GRILLE	CRACKED	820.00	392.00
1	SET FRONT GRILLE CLIPS	NECESSARY	50.00	35.00
1	HEADLAMP O/S	CRACKED	2,880.00	1,200.00
1	HEADLAMP LOWER BRACKET O/S	NOT NECESSARY	199.00	-
1	FRONT SUPPORT PANEL	CRACKED	1,215.00	820.00
1	FRONT FENDER O/S	TO REPAIR SEE LABOUR	885.00	-
1	FRONT FENDER INNER SHIELD O/S	NOT NECESSARY	288.00	-
1	SET FRONT FENDER INNER SHIELD CLIPS O/S	NOT NECESSARY	50.00	-
1	FRONT INTER COOLER	DENTED / PUNCTURE	2,680.00	1,100.00
1	FRONT INTER COOLER BRACKET TOP	CRACKED	100.00	92.00
1	FRONT INTER COOLER GARNISH HOUSING	CRACKED	665.00	455.00
1	FRONT INTER COOLER AIR BOX	CRACKED	980.00	423.00
1	AIR CON CONDENSER	NOT NECESSARY	1,100.00	-
1	RADIATOR	NOT NECESSARY	1,299.00	-
1	RADIATOR FAN ASSY	NOT NECESSARY	800.00	-
1	FRONT LOWER ARM O/S	NOT NECESSARY	620.00	-
1	FRONT KNUCKLE ARM O/S	BENT	755.00	520.00
1	FRONT KNUCKLE ARM BEARING O/S	DAMAGED	350.00	218.00
1	FRONT SHOCK ABSORBER O/S	NOT NECESSARY	488.00	-
1	FRONT STEEL RIM O/S	DENTED / BENT	200.00	80.00

Report Ref No. CC6/CTI21000364/Uea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-	-748.10
			21,722.00	6,732.90
	LABOUR			
	TO CHECK WIRING .		50.00	20.00
	TO REFILL AIR CON GAS.		120.00	100.00
	TO SPRAY RUST PROOFING .	NOT NECESSARY	100.00	-
	TO CONDUCT WHEEL ALIGNMENT .		120.00	80.00
	TO DISMANTLE & REPLACED FRT UNDER CARRIAGE .		180.00	120.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF FRONT FENDER O/S .		1,080.00	600.00
	TO PUTTY & SPRAY PAINTING .		1,500.00	600.00
			3,150.00	1,520.00
	GRAND TOTAL		24,872.00	8,252.90
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,600.00

Report Ref No. CC6/CTI21000364/Uea3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBK 3922M

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBK 3922M

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBK 3922M

RE-INSPECTION

