

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFY 3253P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	BUCKLED	855.00	855.00
1	FRONT BUMPER RETAINER LH	DISTORTED	41.00	41.00
1	FRONT BUMPER BRACKET LH	TO REPAIR SEE LABOUR	52.00	-
1	FRONT BUMPER LOWER SPOILER	DENTED / DISTORTED	399.00	334.00
1	FRONT BUMPER FOG LAMP LH	MTG CRACKED	229.00	229.00
1	SET FRONT BUMPER CLIPS	NECESSARY	40.00	40.00
1	FRONT GRILLE	MTG CRACKED	577.00	577.00
1	BONNET	TO REPAIR SEE LABOUR	997.00	-
1	HEAD LAMP LH	CUT	1,917.00	1,852.00
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	699.00	-
	LESS 10% DISCOUNT		-	-392.80
			5,806.00	3,535.20
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN)	SERVICEABLE	60.00	-
			60.00	-
	<u>LABOUR</u>			
	LABOUR CHARGE TO REMOVE, CUT OUT DAMAGE PORTION, JACK OUT, STRAIGHTEN, PANEL BEATING, WELDING, ALIGN AND RENEW REPLACED PARTS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER BRACKET LH, BONNET AND FRONT SUPPORT PANEL.		1,000.00	500.00
	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS.		900.00	750.00
	TO REMOVE, REPLACE FRONT BONNET FITTINGS TO FACILITATE REPAIR.	NOT NECESSARY	300.00	-
	TO CHECK WIRING AND LIGHTINGS.		80.00	20.00
			2,280.00	1,270.00
	GRAND TOTAL		8,146.00	4,805.20

Report Ref No. CS/FCI21000365/Ktd3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		3,800.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/FCI21000365/Ktd3e2

**KONG SENG CHEONG** 

**Licensed Appraiser**