

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21000371/UGA3Q2
Date: 19/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070027050
Claimant Vehicle No :	SLU7523J	Insured Vehicle No :	GBC688B
Date of Loss:	06/01/2021	Nature of Claim:	TP
		Claim No:	8140274201SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU7523J	Engine No:	3ZRA415807
Make & Model:	TOYOTA WISH, 2.0 (A)	Chassis No:	JTDGJ20W205001472
Reg. Date:	24/12/2009 (Man. Year: 2009)	Odometer:	334894 km
Colour:	Silver		
Engine Capacity:	1987 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/50Z R17	Rear Tyre Size:	225/50Z R17
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,519.83	6,431.90	4,087.93	38.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,970.00	2,320.00	1,650.00	41.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,489.83	8,751.90	5,737.93	39.60
Approved Total (Overridden) (S\$)		7,000.00		

(S\$)	14,489.83	7,000.00	7,489.83	51.69
+ GST 7.00/7.00% (S\$)	1,014.29	490.00	524.29	51.69
Nett Amount (S\$)	15,504.12	7,490.00	8,014.12	51.69
+ Loss of Use (7.0 x S\$80.00/day) (S\$)		560.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		8,057.45		

INSPECTION

Date of Assignment: 08/01/2021

Date Inspected: 08/01/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Teamwork Garage Pte Ltd (HQ)
 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park
 Singapore 408934

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	764.75 FL	*566.01 FL
2	2		*REAR BUMPER SIDE BRACKET	Not Necessary	150.92 FL	*- FL
3	2		*REAR BUMPER SIDE RETAINER	Not Necessary	139.26 FL	*- FL
4	2		*REAR BUMPER DAMPER	Not Necessary	281.30 FL	*- FL
5	1		*REAR BUMPER REFLECTOR	O/S Cracked	115.56 FL	*57.78 FL
6	1		*REAR END PANEL	Badly Dented	503.47 FL	*503.47 FL
7	1		*REAR END PANEL TOP GARNISH	Twisted	182.62 FL	*182.62 FL
8	1		*REAR LOWER INNER PANEL	Badly Dented	589.20 FL	*245.50 FL
9	1		*FLOOR PANEL	Repair	583.40 FL	*- FL
10	1		*FLOOR PANEL INNER GARNISH	Cracked	316.20 FL	*316.20 FL
11	1		*FLOOR PANEL TOP BOARD	Not Necessary	301.45 FL	*- FL
12	1		*REAR TAILAMP	O/S Cracked	652.51 FL	*326.25 FL
13	2		*REAR TAILAMP INNER SEAL	Not Necessary	30.00 FL	*- FL
14	1		*REAR FENDER INNER TRIM	O/S Cracked	793.84 FL	*396.92 FL
15	1		*EXHAUST SILENCER	Repair	791.34 FL	*- FL
16	2		*EXHAUST MOUNTING	Not Necessary	30.00 FL	*- FL
17	1		*TAILGATE	Badly Dented	1,314.33 FL	*1,314.33 FL
18	2		*TAILGATE ABSORBER	Not Necessary	346.43 FL	*- FL
19	1		*TAILGATE EMBLEM LOGO	Necessary	31.00 FL	*31.00 FL
20	1		*TAILGATE EMBLEM	Necessary	49.00 FL	*49.00 FL
21	1		*TAILGATE OUTER CHROME	Cracked	219.50 FL	*219.50 FL
22	1		*TAILGATE WEATHERSTRIP	Twisted	309.10 FL	*309.10 FL
23	1		*TAILGATE GLASS MOULDING	Necessary	180.00 FL	*128.10 FL
24	1		*TAILGATE LOCK	Dented	509.30 FL	*509.30 FL
25	1		*TAILGATE LOCK STRIKER	Not Necessary	54.20 FL	*- FL
26	2		*TAILGATE HINGE	Not Necessary	131.70 FL	*- FL
27	1		*TAILGATE INNER TRIM BOARD	Deformed / Torn	680.20 FL	*485.10 FL
28	1		*REAR WINDSCREEN	Shattered	1,065.90 FL	*1,065.90 FL
29	2		*REAR WINDSCREEN MOULDING	Repeated	120.00 FL	*- FL
30	1		*WIPER	Not Necessary	42.60 FL	*- FL
31	1		*WIPER MOTOR	Bent / Jammed	800.00 FL	*509.10 FL
32	1		*TAILGATE LAMP (2 PCS)	Cracked	920.69 FL	*920.69 FL
33	1		*SET REAR BUMPER CLIP	Necessary	40.00 FS	*40.00 FS
34	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	30.00 FS	*- FS
35	1		*SET REAR REVERSE SENSOR	Shorted	400.00 FS	*200.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*JOINT SEALANT	Necessary	150.00 FS	*50.00 FS
37	1		*WINDSCREEN SEALANT	Necessary	150.00 FS	*40.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					13,769.77	8,465.87
- List Item Discount on L Items 25.00/25.00% (\$)					3,249.94	2,033.97
Total Parts (\$)					10,519.83	6,431.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK REAR WIRING AND LIGHTING SYSTEM	New	60.00	30.00
2	REMOVE ,REFIT REAR LINING ,TRIM AND GARNISH	New	200.00	80.00
3	REMOVE AND RENEW REAR REVERSE SENSOR	New	120.00	50.00
4	REMOVE AND RENEW EXHAUST ASSY	New	150.00	0.00
5	REMOVE AND REFIT REAR WINDSCREEN	New	120.00	120.00
6	TRANSFER PARTS ,ATTACHMENT FROM OLD TAILGATE TO NEW	New	200.00	60.00
7	PANEL BEATING ON AFFECTED AREAS	New	1,400.00	900.00
8	SPRAY PAINTING ON AFFECTED AREAS	New	1,600.00	1,000.00
9	APPLY ANTI RUST ON AFFECTED AREAS	New	120.00	80.00
Gross Labour Cost (\$\$)			3,970.00	2,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >