

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMQ 9272D

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SIDE LAMP ASSY-RH	SCRATCHED	623.75	623.75
1	SIDE LAMP CHROME-RH	SCRATCHED	123.20	123.20
1	HEADLAMP ASSY-RH	CRACKED	847.50	847.50
1	FRONT BUMPER	BUCKLED / DENTED	1,767.60	1,767.60
1	FRONT BUMPER SIDE RETAINER-RH	SERVICEABLE	118.00	-
2	FRONT BUMPER SENSOR @\$198.00	SERVICEABLE	396.00	-
6	FRONT BUMPER SENSOR SEALS @\$12.00	NECESSARY	72.00	72.00
	LESS 10% DISCOUNT		-394.80	-343.40
			3,553.25	3,090.65
15	FRONT BUMPER CLIPS @\$5.50 (SN) LESS 10% DISCOUNT	NECESSARY	82.50 -8.25	50.00
			74.25	50.00
	<u>LABOUR</u>			
	TO CHECK AND RECTIFY WIRING SYSTEM.		80.00	20.00
	TO REMOVE AND REFIX FRONT BUMPER SENSOR.		100.00	60.00
	TO PANEL BEAT AND STRAIGHTEN RH FRONT CHASSIS FRAME,INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY TO REFIT AND ADJUST THE SAME.		800.00	300.00
	TO PUTTY AND SPRAY SAME ON AFFECTED AREAS.		800.00	400.00
	TO APPLY RUST PROOFING ON REPAIRED AND REPLACED PANELS.	NOT NECESSARY	100.00	-
			1,880.00	780.00
	GRAND TOTAL		5,507.50	3,920.65

RECOMMENDED COST OF REPAIRS			3,920.65
-----------------------------	--	--	----------

Report Ref No. CS/AGI21000376/Ktd3q2

KONG SENG CHEONG

Licensed Appraiser