

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21000379/UTD3Q2

Date: 15/01/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNA00003482000

Claimant Vehicle No : SMN5874J **Insured Vehicle No :** SMS750P

Date of Loss: 26/12/2020 Nature of Claim: TP Claim No: SNM20D205177/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMN5874J**
 Make & Model: MERCEDES-BENZ A180, 1.6 (A) Engine No: 27091031061593
 Reg. Date: 24/01/2017 (Man. Year: 2016) Chassis No: WDD1760422J507998
 Colour: Red Odometer: 54163 km
 Engine Capacity: 1595 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40R18 Rear Tyre Size: 225/40R18
 Front Left Side: General 6 mm Rear Left Side: General 6 mm
 Front Right Side: General 6 mm Rear Right Side: General 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,508.67	5,874.36	15,634.31	72.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,210.00	1,780.00	1,430.00	44.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,718.67	7,654.36	17,064.31	69.03
Approved Total (Overridden) (S\$)		6,100.00		
Nett Amount (S\$)	24,718.67	6,100.00	18,618.67	75.32

INSPECTION

Date of Assignment: 08/01/2021

Date Inspected: 08/01/2021 Inspected At: Asia Motorsports-kaki Bukit (HQ)
 15 KAKI BUKIT ROAD 4 #01-05/53
 BARTLEY BIZ CENTRE
 Singapore 417808

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 15 Jan 2021)	
Parts:	N/A	MERCEDES-BENZ A180 1.6 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMN5874J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY (AMG) (SPORT)	Distorted/Cracked	3,200.10 FL	*1,800.00 FL
2	2		*REAR BUMPER SIDE RETAINER	Bent	184.20 FL	*184.20 FL
3	1		*REAR BUMPER RETAINER	Twisted	159.10 FL	*159.10 FL
4	1		*REAR BUMPET TOW COVER	Not Necessary	98.80 FL	*- FL
5	1		*REAR BUMPER REINFORCEMENT	Bent	650.80 FL	*465.00 FL
6	1		*REAR BUMPER SPOILER AIR VENT COVER N/S	Cut	350.10 FL	*220.00 FL
7	1		*REAR TAILGATE ASSY	Repair	3,655.10 FL	*- FL
8	1		*REAR TAILGATE LOCK MECHANISM	Not Necessary	380.50 FL	*- FL
9	1		*REAR TAILGATE AMG EMBLEM	Necessary	155.80 FL	*98.00 FL
10	1		*REAR TAILGATE CENTRE LOGO	Not Necessary	175.50 FL	*- FL
11	1		*REAR TAILGATE WEATHERSTRIP	Twisted	298.10 FL	*182.65 FL
12	1		*REAR TAILGATE INNER BOARD	Not Necessary	288.10 FL	*- FL
13	1		*REAR TAILGATE NUMBER PLATE LAMP	Not Necessary	88.10 FL	*- FL
14	1		*REAR WINDSCREEN GLASS MOULDING	Not Necessary	288.80 FL	*- FL
15	1		*REAR LEFT TAILLAMP	Cracked	1,093.50 FL	*587.52 FL
16	1		*REAR RIGHT TAILLAMP	Not Necessary	1,093.50 FL	*- FL
17	1		*REAR END PANEL	Dented/Bent	1,443.70 FL	*775.42 FL
18	1		*REAR END PANEL TOP GARNISH	Twisted/Cracked	272.50 FL	*199.62 FL
19	1		*SET REAR BUMPER CLIPS & REVERT	Necessary	100.00 FS	*60.00 FS
20	1		*REAR END PANEL SEALANT	Necessary	150.00 FS	*50.00 FS
21	6		*REAR END LOWER PANEL TOP GARNISH CLIPS	Not Necessary	45.00 FS	*- FS
22	1		*REAR BUMPER REVERSE SENSOR 6 Pcs	Shorted (2 Pcs only)	2,500.00 FS	*360.00 FS
23	1		*REAR NO PLATE WITH GARNISH	Not Necessary	100.00 FS	*- FS
24	1		*REAR LEFT EXHAUST END TAIL PIPE	Not Necessary	450.00 FS	*- FS
25	1		*REAR RIGHT EXHAUST END TAIL PIPE	Not Necessary	450.00 FS	*- FS
26	10		*REAR TAILGATE INNER BOARD CLIPS	Not Necessary	45.00 FS	*- FS
27	1		*REAR BUMPER LOWER SPOILER SPORT	Distorted	1,600.00 FS	*1,200.00 FS
28	10		*REAR BUMPER LOWER SPOILER CLIPS	Not Necessary	65.00 FS	*- FS
29	1		*REAR BUMPER LOWER SPOILER SEALANT	Not Necessary	100.00 FS	*- FS
30	1		*REAR BUMPER LOWER DIFFUSER	Repair	2,800.00 FS	*- FS
31	1		*REAR BUMPER LOWER DIFFUSER SEALANT	Not Necessary	100.00 FS	*- FS
32	10		*REAR BUMPER LOWER DIFFUSER CLIPS	Not Necessary	65.00 FS	*- FS
33	1		*REAR VIEW CAMERA	Not Necessary	350.00 FS	*- FS
34	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 22,896.30 6,341.51
- List Item Discount on L Items 10.00/10.00% (\$\$) 1,387.63 467.15

Total Parts (\$\$) 21,508.67 5,874.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN REAR AFFECTED AREA AND REPLACE REAR DAMAGED PARTS	New	1,200.00	800.00
2	TO PUTTY AND SPRAY PAINTING REAR PORTION	New	1,200.00	800.00
3	TO CHECK REAR LIGHTING AND WIRING	New	50.00	20.00
4	TO REMOVE AND INSTALL REAR TAILGATE LOCK MECHANISM	New	80.00	0.00
5	TO REMOVE AND INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR	New	140.00	80.00
6	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA	New	140.00	30.00
7	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR	New	80.00	50.00
8	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE THE REPAIR	New	140.00	0.00
9	TO REMOVE AND INSTALL REAR VIEW CAMERA	New	80.00	0.00
10	TOWING SERVICE	New	100.00	0.00
Gross Labour Cost (\$\$)			3,210.00	1,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >