

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21000380/BQD3E2

Date: 29/04/2021

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00061442000

Claimant Vehicle No : SLR9227S

Insured Vehicle No : GBH6410U

Date of Loss: 26/12/2020

Nature of Claim: TP

Claim No: SNM20D205136/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLR9227S**

Make & Model: MAZDA 3, 1.4 SEDAN 1.5L SP.6EAT (A)

Engine No: P520282166

Reg. Date: 11/05/2015 (Man. Year: 2015)

Chassis No: JM6BM42A8G0310220

Colour: White

Odometer: 93723 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Michelin 7 mm

Rear Left Side: Michelin 7 mm

Front Right Side: Michelin 7 mm

Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,043.09	2,207.96	4,835.13	68.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,720.00	1,290.00	2,430.00	65.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,763.09	3,497.96	7,265.13	67.50
Approved Total (Overridden) (S\$)		2,800.00		
(S\$)	10,763.09	2,800.00	7,963.09	73.99
+ GST 7.00/7.00% (S\$)	753.42	196.00	557.42	73.99
Nett Amount (S\$)	11,516.51	2,996.00	8,520.51	73.99

INSPECTION

Date of Assignment: 08/01/2021

Date Inspected: 11/01/2021

Inspected At:

Team Autopro Pte Ltd (Sin Ming)
160 SIN MING DR
#01-14 SIN MING AUTO CITY
SINGAPORE 575722

Estimated Period of Repair: 5.0 days

Adjuster: Lim Teow Guan

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Apr 2021)
Parts:	143	MAZDA 3 1.4 SEDAN 1.5L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR9227S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	1,358.00 FL	*- FL
2	1		*BOOTLID LOGO	Necessary	88.20 FL	*57.15 FL
3	1		*BOOTLID EMBLEM AZDA	Necessary	68.90 FL	*36.00 FL
4	1		*BOOTLID EMBLEM SKYACTIV	Necessary	87.20 FL	*75.90 FL
5	1		*BOOTLID INNER LOCK	Not Damaged	190.80 FL	*- FL
6	1		*BOOTLID INNER LOCK STRIKER	Not Damaged	68.10 FL	*- FL
7	1		*BOOTLID ANTENNA SENSOR	Not Damaged	358.60 FL	*- FL
8	1		*REAR BUMPER	Broken	1,096.70 FL	*949.00 FL
9	2		*REAR BUMPER SIDE RETAINER	Not Necessary	137.80 FL	*- FL
10	1		*REAR BUMPER REINFORCEMENT	Bent	684.20 FL	*573.30 FL
11	2		*REAR BUMPER REFLECTOR	Not Necessary	156.46 FL	*- FL
12	2		*REAR BUMPER TOW CAP	Dented	82.00 FL	*34.00 FL
13	1		*REVERSE SENSOR (4PCS)	Short Circuit (2Pcs Only)	1,074.00 FL	*400.00 FL
14	1		*REAR END PANEL	Dented	730.40 FL	*559.60 FL
15	1		*REAR END PANEL TOP GARNISH	Not Damaged	109.40 FL	*- FL
16	1		*REAR EXHAUST PIPE	Not Damaged	1,544.00 FL	*- FL
17	2		*REAR EXHAUST PIPE MOUNTING	Not Damaged	131.60 FL	*- FL
18	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
19	1		*BOOTLID SEALANT	Not Necessary	100.00 FS	*- FS
20	1		*BOOTLID INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
21	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
22	4		*REVERSE SENSOR SEAL	No such part	240.00 FS	*- FS
23	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
24	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,636.36	2,744.95
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,593.27	536.99

Total Parts (\$\$)	7,043.09	2,207.96
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R BOOTLID COMPONENT	New	150.00	0.00
2	R&R REVERSE SENSOR	New	100.00	60.00
3	R&R REAR EXHAUST PIPE	New	150.00	0.00
4	UPHOLSTERY	New	200.00	0.00
5	CHECK WIRING	New	100.00	0.00
6	DIAGNOSTIC RESET FAULT CODE	New	300.00	0.00
7	CONDUCT WATER LEAK TEST	New	120.00	0.00
8	PANEL BEAT	New	1,200.00	600.00
9	RUST PROOFING	New	200.00	30.00
10	SPRAY PAINTING	New	1,200.00	600.00
Gross Labour Cost (\$\$)			3,720.00	1,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >