

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD CS3/ASM21000383/Eqd3e2 Ref: 8 SHENTON WAY #24-01 AXA Date: 29/01/2021 **TOWERSINGAPORE 068811** ATTN: PETER WANG Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SKM 9063K SGM 2597E Veh. Inspected Policy No. GA460584/1 Coverage (\$) 0.00 Claim No. S1M02ZY4 Excess (\$) 0.00 PETER WANG **Assign Date** 08/01/2021 Assign From **Vehicle Particulars & Condition** 2. TOYOTA ESTIMA Make & Model 2362 C.C HIDDEN 2006 Engine No. Year of Reg. ACR507019522 GOLD Chassis No. Colour Odometer 122135 KM Steering IN ORDER IN ORDER SPORTS RIM **Brakes** Modification **FAIR** General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 225/50 R18 MICHELIN 4 mm **MICHELIN** L/H Front Tyre 225/50 R18 4 mm 225/50 R18 **MICHELIN** R/H Rear Tyre 4 mm MICHELIN L/H Rear Tyre 225/50 R18 4 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. 5. **General Information** 04/01/2021 Inspect Date / Time 11/01/2021 (10:00 AM) Accident Date **GOLD AUTOWORKS PTE LTD** Survey held at 48 TOH GUAN ROAD EAST #01-119 ENTERPRISE HUB SINGAPORE 608586 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$7,000

Report Ref No. CS3/ASM21000383/Eqd3e2

Estimate Days of Repair

Inspected By

ESTIMATED NORMAL PERIOD FOR REPAIR:

5b.

CHEN TSUE YEE

Automotive Assessor

L

K.K.LAU CPT(RET)

DE :: (Harra) D D.:: MDA DE:: :: DE H

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

7 Working Days