



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Ref: CS3/III20011789/Gqd3e2-1	
			Date: 08/02/2021	
			Code: III2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	PC 1632P	Veh. Inspected	SLE 5482R
	Policy No.	D20MFL0003256	Coverage (\$)	0.00
	Claim No.	MFL2020D0002221	Excess (\$)	0.00
	Assign From	CARINE KHEK	Assign Date	08/01/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	VOLVO V50 2.0L	c.c	1999
	Engine No.	HIDDEN	Year of Reg.	2010
	Chassis No.	YV1MW434BA2559065	Colour	BLUE
	Odometer	170027 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	225/45 R17	DUNLOP	6 mm
	L/H Front Tyre	225/45 R17	DUNLOP	6 mm
	R/H Rear Tyre	225/45 R17	DUNLOP	6 mm
	L/H Rear Tyre	225/45 R17	DUNLOP	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.  DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	26/10/2020	Inspection Date	29/10/2020
	Survey held at	LKT GROUP PTE LTD 3006 UBI ROAD 1 #01-384 KAMPONG UBI INDUSTRIAL ESTATE SINGAPORE 408700		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	