

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21000403/DBA3Q2
Date: 06/09/2021**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Claimant Vehicle No : GBJ1788C

Date of Loss: 27/12/2020

Policy No:

Insured Vehicle No :

SLX396P

Nature of Claim:

TP

Claim No:

0580645739SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBJ1788C**

Make & Model: TOYOTA DYNA 150, 3.0 D 5MT (M)

Reg. Date: 16/01/2019 (Man. Year: 2018)

Colour: Silver

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 1KD2837098

Chassis No: JTFAT35Y30K212270

Odometer: 33942 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 195/75 R15

Front Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm

Rear Tyre Size:

155 R12 (D)

Rear Left Side:

Bridgestone 5/5 mm

Rear Right Side:

Bridgestone 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,112.28	1,010.57	15,101.71	93.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,500.00	1,070.00	6,430.00	85.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,612.28	2,080.57	21,531.71	91.19
Approved Total (Overridden) (S\$)		1,650.00		

(S\$)	23,612.28	1,650.00	21,962.28	93.01
+ GST 7.00/7.00% (S\$)	1,652.86	115.50	1,537.36	93.01
Nett Amount (S\$)	25,265.14	1,765.50	23,499.64	93.01
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 28/12/2020

Date Inspected: 29/12/2020

Estimated Period of Repair: 4.0 days

Inspected At:

JWG International Pte Ltd (HQ)
 Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint
 Singapore 568047

Adjuster: BRYAN TANI**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Repair	2,179.00 FL	*- FL
2	1		*REAR TAILGATE HINGE	Serviceable	308.10 FL	*- FL
3	2		*REAR TAILGATE LOCK LH /RH	Not Necessary	434.62 FL	*- FL
4	2		*REAR TAILGATE LOCK BRACKET LH/RH	Not Necessary	214.40 FL	*- FL
5	2		*REAR TAILGATE STOPPER LH/RH	Serviceable	143.56 FL	*- FL
6	2		*REAR TAILGATE STOPPER BRACKET LH/RH	Not Necessary	264.18 FL	*- FL
7	2		*REAR SIDE GATE LH/RH	Not Necessary	3,909.44 FL	*- FL
8	2		*TAIL LAMP LH/RH	Not Necessary	907.40 FL	*- FL
9	2		*TAIL LAMP BRACKET LH/RH	Not Necessary	271.64 FL	*- FL
10	1		*REAR END PANEL	Dented	1,074.59 FL	*727.43 FL
11	1		*REAR FLOOR PANEL	Not Necessary	2,880.90 FL	*- FL
12	2		*CHASSIS BRACKET	Not Necessary	629.04 FL	*- FL
13	1		*REAR NO PLATE LAMP	Not Necessary	107.20 FL	*- FL
14	1		*SPARE TYRE BRACKET	Not Necessary	498.56 FL	*- FL
15	1		*SPARE TYRE BOLT	Not Necessary	310.80 FL	*- FL
16	1		*SPARE TYRE HOLDER	Not Necessary	541.92 FL	*- FL
17	1		*REAR EXHAUST PIPE	Not Necessary	1,345.29 FL	*- FL
18	1		*REAR EXHAUST MOUNTING	Not Necessary	182.40 FL	*- FL
19	1		*REAR NUMBER PLATE	Bent	100.00 FS	*15.00 FS
20	1		*FLOOR PANEL SEALANT	Not Necessary	80.00 FS	*- FS
21	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*40.00 FS
22	1		*REAR STEP REAR	Bent	800.00 FS	*150.00 FS
23	1		*70KM STICKER	Necessary	50.00 FS	*15.00 FS
24	1		*TAILGATE CHECKERED PLATE	Not Necessary	1,000.00 FS	*- FS
25	1		*TAILGATE 6 PAX STICKER	Necessary	50.00 FS	*15.00 FS
26	1		*TAILGATE ADVERTISEMENT STICKER (TOYOTA)	Necessary	1,500.00 FS	*80.00 FS
27	1		*REVERSE SENSOR	Damaged	300.00 FS	*150.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	20,163.04	1,192.43
- List Item Discount on L Items 25.00/25.00% (\$)	4,050.76	181.86
Total Parts (\$)	16,112.28	1,010.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RNR REAR METAL DECK TO FACILITATE REPAIRS	New	1,800.00	0.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,400.00	500.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,400.00	500.00
4	TO RNR REVERSE SENSOR TO FACILITATE REPAIRS	New	200.00	40.00
5	TO TUFF COAT DAMAGED AREAS	New	300.00	30.00
6	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	150.00	0.00
7	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	New	250.00	0.00
Gross Labour Cost (S\$)			7,500.00	1,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >