LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way, #09-16

Our File No: CC3/AIG21000404/AVD3E2

Singapore 079120 Date: 07/05/2021

REFERENCE

Insured/Claimant: CHEONG HENG LIM Policy No: 2100431329

Date of Loss: 02/01/2021 Nature of Claim: OD Claim No: 5907904900SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKV6958B

Make & Model: AUDI A3, 1.4 SEDAN TFSI COD S-TRONIC (A) Engine No: CZC267121

Reg. Date: 29/09/2015 (Man. Year: 2015) Chassis No: WAUZZZ8V3G1005440

Colour: Grey Odometer: 59085 km

Engine Capacity: 1395 cc
Market Value/New Car Price: \$\$62,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		6,411.00	2,816.16	3,594.84	56.07
Miscellaneous Items		0.00	0.00	0.00	
Labour		7,582.00	3,352.00	4,230.00	55.79
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	13,993.00	6,168.16	7,824.84	55.92
	- Excess (S\$)	600.00	600.00	0.00	0.00
	(S\$)	13,393.00	5,568.16	7,824.84	58.42
	+ GST 7.00/7.00% (S\$)	937.51	389.77	547.74	58.42
	Nett Amount (S\$)	14,330.51	5,957.93	8,372.58	58.42

INSPECTION

Date of Assignment: 10/01/2021

Date Inspected: 08/01/2021 Inspected At: Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER - LH	Dented	841.00 FS	*672.80 FS
2	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	71.00 FS	*- FS
3	1		*FRONT FENDER BRACKET - LH	Not Necessary	27.00 FS	*- FS
4	1		*WHEEL HOUSING LINER - LH	Not Necessary	167.00 FS	*- FS
5	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	88.00 FS	*- FS
6	1		*FRONT DOOR - LH	Dented	2,494.00 FS	*1,995.20 FS
7	1		*FRONT DOOR OUTER SEAL - LH	Necessary	159.00 FS	*127.20 FS
8	1		*BONDING AGENT	Not Necessary	47.00 FS	*- FS
9	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
10	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	238.00 FS	*- FS
11	1		*FRONT DOOR CATCH	Not Necessary	104.00 FS	*- FS
12	1		*EXTERIOR MIRROR MOUNTING - LH	Not Necessary	1,013.00 FS	*- FS
13	1		*MIRROR CAP - LH	Not Necessary	148.00 FS	*- FS
14	1		*FRONT ALUMINIUM RIM - LH	Not Necessary	699.00 FS	*- FS
15	1		*SUNDRIES	Necessary	250.00 FS	*20.96 FS
F=Fra	ınchise	part. S=SpcN	Nett.	-		
				Total Parts (S\$)	6,411.00	2,816.16
			Report was unsubmitted during th	is print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	280.00	0.00
2	TO DISMANTLE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW LHS WING MIRROR ASSY	New	350.00	280.00
3	TO REMOVE AND TRANSFER LHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	280.00	280.00
4	TO DISMANTLE FRONT BUMPER, LHS FRONT FENDER AND LHS FRONT DOOR. TO RENEW LHS FRONT FENDER AND LHS FRONT DOOR. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,800.00	1,500.00
5	TO RESPRAY LHS FRONT FENDER, LHS FRONT DOOR, LHS WING MIRROR COVER AND LHS SILL PANEL	New	3,400.00	1,100.00
6	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
	Gross Labou	ır Cost (S\$)	7,582.00	3,352.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >