

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG21000406/AGA3Q2

Date: 13/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800001622

Claimant
Vehicle No : SMP7942Y **Insured Vehicle No :** SLV6793Y

Date of Loss: 08/01/2021 Nature of Claim: TP Claim No: 6105268260SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP7942Y		
Make & Model:	AUDI A6, 2.0 (A)	Engine No:	DLH054572
Reg. Date:	16/10/2019 (Man. Year: 2019)	Chassis No:	WAUZZZF23KN123109
Colour:	Grey	Odometer:	12655 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R19	Rear Tyre Size:	245/45 R19
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,584.00	3,315.12	2,268.88	40.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,552.00	2,152.00	2,400.00	52.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,136.00	5,467.12	4,668.88	46.06
+ GST 7.00/7.00% (S\$)	709.52	382.70	326.82	46.06
Nett Amount (S\$)	10,845.52	5,849.82	4,995.70	46.06
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,251.82		

INSPECTION

Date of Assignment: 13/01/2021

Date Inspected: 13/01/2021 Inspected At:

Premium Automobiles Pte Ltd (HQ)
55 UBI ROAD 1
Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,832.00 FS	*2,265.60 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	236.00 FS	*- FS
3	1		*REAR BUMPER SPOILER	Deformed	885.00 FS	*708.00 FS
4	2		*REAR BUMPER TRIM -LH/RH	Not Necessary	490.00 FS	*- FS
5	1		*REAR BUMPER TRIM -CENTER	Not Necessary	173.00 FS	*- FS
6	1		*REAR BUMPER SECURING STRIP	Necessary	172.00 FS	*137.60 FS
7	1		*AERIAL KEY SENSOR	Not Necessary	184.00 FS	*- FS
8	2		*REAR LIGHT REFLECTOR LH/RH	Not Necessary	82.00 FS	*- FS
9	2		*REAR LIGHT REFLECTOR INNER -LH/RH	Not Necessary	60.00 FS	*- FS
10	1		*REAR SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
11	4		*REAR SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
12	1		*REAR PACKING ADHESIVE	Necessary	19.00 FS	*14.88 FS
13	1		*REAR AUDI EMBLEM	Necessary	138.00 FS	*110.00 FS
14	1		*REAR INSCRIPTION A6	Necessary	99.00 FS	*79.04 FS
15	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS
					Total Parts (\$\$)	5,584.00 3,315.12

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR ,CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER .TO REPAIR REAR LID .RE-ORGANIZE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	1,600.00	500.00
3	TO RESPRAY REAR BUMPER AND REAR LID	New	2,400.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			4,552.00	2,152.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >