

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21000407/TPS3Q2**Date:** 14/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100486287
Claimant Vehicle No :	SHC7537L	Insured Vehicle No :	SLG8227G
Date of Loss:	07/01/2021	Nature of Claim:	TP
		Claim No:	2190854048SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC7537L		
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Engine No:	HIDDEN
Reg. Date:	09/01/2019 (Man. Year: 2019)	Chassis No:	JTDKB3FU503078304
Colour:	Yellow	Odometer:	327975 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,587.02	1,441.40	1,145.62	44.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,700.00	1,080.00	620.00	36.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,287.02	2,521.40	1,765.62	41.19
+ GST 7.00/7.00% (S\$)	300.09	176.50	123.59	41.18
Nett Amount (S\$)	4,587.11	2,697.90	1,889.21	41.19
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$126.47/day) (S\$)		379.41		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,229.31		

INSPECTION

Date of Assignment:	08/01/2021	
Date Inspected:	08/01/2021	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FRONT BUMPER	Repair	499.90 FL	*- FL
2	1		*FENDER SUB-ASSY FRO	Repair	945.30 FL	*- FL
3	1		*EMBLEM SIDE PANEL	Necessary	86.50 FL	*86.50 FL
4	1		*SUPPORT FRONT BUMPER	Not Necessary	82.30 FL	*- FL
5	1		*(I40)FRT DOOR LOGO CCTPL	Necessary	80.00 FS	*80.00 FS
6	1		*MIRROR ASSY	Deformed	1,728.70 FL	*1,728.70 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					3,422.70	1,895.20
- List Item Discount on L Items 25.00/25.00% (\$\$)					835.68	453.80
Total Parts (\$\$)					2,587.02	1,441.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	350.00
2	SPRAYPAINT CHARGE	New	600.00	500.00
3	CHECK ALL LIGHTING	New	50.00	30.00
4	TUFF COAT ON AFFECTED PARTS	New	50.00	0.00
5	RENEW ADVERTISEMENT STICKER -DOOR	New	100.00	100.00
6	RENEW ADVERTISEMENT STICKER -FENDER	New	100.00	100.00
Gross Labour Cost (\$)			1,700.00	1,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >