

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21000409/UGA3Q2
Date: 20/12/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100380680
Claimant Vehicle No :	SMC8670T	Insured Vehicle No :	SKN9078M
Date of Loss:	06/01/2021	Nature of Claim:	TP
		Claim No:	2907478045SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC8670T	Engine No:	3A92UGX8215
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Chassis No:	MMBSTA13AJH002138
Reg. Date:	26/07/2018 (Man. Year: 2018)	Odometer:	13513 km
Colour:	Red		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,850.86	5,676.40	5,174.46	47.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,870.00	2,550.00	1,320.00	34.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,720.86	8,226.40	6,494.46	44.12
Approved Total (Overridden) (S\$)		6,600.00		

Nett Amount (S\$)	14,720.86	6,600.00	8,120.86	55.17
+ Car Rental (9.0 x S\$100.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		7,536.45		
Global Sum Settlement (S\$)		7,500.00		

INSPECTION

Date of Assignment: 08/01/2021

Date Inspected: 11/01/2021

Estimated Period of Repair: 8.0 days

Inspected At:

Zoom Autowerks Pte Ltd (HQ)
 15 Kaki Bukit Road 4, Bartley Biz Centre, #01-53
 Singapore 417808

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	758.40 FL	*748.00 FL
2	2		*REAR BUMPER SIDE RETAINER	Not Necessary	130.00 FL	*- FL
3	2		*REAR BUMPER BRACKET	Not Necessary	156.00 FL	*- FL
4	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FL	*40.00 FL
5	1		*REAR BOOTLID PANEL	Dented / Buckled	876.50 FL	*791.00 FL
6	1		*REAR BOOTLID CHROME MOULDING	Not Necessary	318.50 FL	*- FL
7	1		*REAR BOOTLID INNER LOCK	Twisted	286.40 FL	*218.00 FL
8	1		*REAR BOOTLID CATCH	Not Necessary	38.70 FL	*- FL
9	1		*REAR BOOTLID LOGO	Necessary	98.20 FL	*69.00 FL
10	1		*REAR BOOTLID NAME PLATE (MIVEC)	Necessary	78.40 FL	*60.00 FL
11	1		*REAR BOOTLID NAME PLATE (ATTRAGE)	Necessary	95.60 FL	*69.00 FL
12	1		*REAR BOOTLID WEATHER STRIP	Twisted	210.50 FL	*157.00 FL
13	1		*REAR BOOTLID KEYLESS SENSOR	Cracked	286.20 FL	*286.20 FL
14	2		*REAR TAILLAMPS	Scratched / Cracked	1,370.80 FL	*670.00 FL
15	1		*REAR END PANEL	Badly Dented	825.40 FL	*425.00 FL
16	1		*REAR END PANEL TOP GARNISH	Twisted	215.80 FL	*215.80 FL
17	1		*REAR END PANEL SIDE GARNISH N/S	Distorted	60.00 FL	*60.00 FL
18	1		*REAR FENDERS (NPA)	Repair	0.00 FL	*- FL
19	1		*REAR FENDER INNER TRIM GARNISH	N/S Twisted	771.40 FL	*292.00 FL
20	1		*REAR FENDER INNER TRIM GARNISH CLIPS	Not Necessary	80.00 FL	*- FL
21	2		*REAR FENDER INNER SHIELD	Not Necessary	352.00 FL	*- FL
22	1		*REAR FENDER INNER SHIELD CLIPS	Not Necessary	80.00 FL	*- FL
23	1		*REAR SPARE TYRE TOP BOARD	Torn	265.40 FL	*195.00 FL
24	2		*REAR SPARE TYRE TOP FOAM	Not fitted	651.20 FL	*- FL
25	1		*REAR SPARE TYRE PANEL	Repair	980.00 FL	*- FL
26	1		*REAR TAILLAMP PANEL SEALANT	Not Necessary	60.00 FS	*- FS
27	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*50.00 FS
28	1		*REAR SPARE TYRE PANEL SEALANT	Not Necessary	80.00 FS	*- FS
29	1		*REAR BUMPER LOWER GARNISH (ACCESSORIES)	Cracked	1,620.00 FS	*1,500.00 FS
30	2		*REAR EXHAUST MUFFLER CHROME	Not Necessary	510.00 FS	*- FS
31	1		*REAR NUMBER PLATE W/BASE GARNISH & SEAL	Necessary	80.00 FS	*60.00 FS
32	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,755.40	6,106.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	904.54	429.60

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	10,850.86
						5,676.40
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REPAIR & RENEW REAR AFFECTED ACCIDENT AREAS	New	1,200.00	1,000.00
2	TO PUTTY ,SPRAY PAINT ON AFFECTED ACCIDENT AREAS	New	1,600.00	1,200.00
3	TO TOW & INSPECT LTA TO BREAK WEEKEND SEAL	New	250.00	50.00
4	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	30.00
5	TO REMOVE & INSTALL REAR BOOTLID COMPONENTS TRIM & GARNISH	New	150.00	60.00
6	TO REMOVE & INSTALL REAR FENDERS TRIM ,GARNISH	New	150.00	80.00
7	TO RE-POSITION & ALIGN REVERSE SENSOR	New	120.00	50.00
8	TO CONDUCT WATER LEAKAGE TEST	New	150.00	0.00
9	TO RUST PROOF AFFECTED AREAS	New	200.00	80.00
Gross Labour Cost (\$\$)			3,870.00	2,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >