

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21000410/EVD3E2**Date:** 05/07/2021**REFERENCE**

Insured/Claimant: NG BOON CHYE ANDREW @ ADHWA NG ABDULLAH
Date of Loss: 08/01/2021

Policy No:
Nature of Claim: OD Claim No: 2124307583SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA6469H	Engine No:	D4FDJH551779
Make & Model:	KIA CARENS, 1.7 DCT (A)	Chassis No:	KNAHU815VJ7205410
Reg. Date:	26/04/2018 (Man. Year: 2018)	Odometer:	57783 km
Colour:	White		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	S\$79,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,319.20	4,797.60	4,521.60	48.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,700.00	4,850.00	2,850.00	37.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,019.20	9,647.60	7,371.60	43.31
- Excess (S\$)	3,000.00	3,000.00	0.00	0.00
(S\$)	14,019.20	6,647.60	7,371.60	52.58
+ GST 7.00/7.00% (S\$)	981.34	465.33	516.01	52.58
Nett Amount (S\$)	15,000.54	7,112.93	7,887.61	52.58

INSPECTION

Date of Assignment:	11/01/2021	
Date Inspected:	11/01/2021	Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	12.0 days	

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
2	1		*WHEEL ASSY-ALUMINIUM	Cut	704.00 FN	*500.00 F
3	1		*COVER-FR BUMPER	Broken	695.00 FL	*695.00 FL
4	1		*EMBLEM-KIA	Necessary	76.00 FL	*76.00 FL
5	1		*BRACKET-FR BUMPER UPR SIDE MTG	Not Necessary	12.00 FL	*- FL
6	1		*BRACKET-FR BUMPER SIDE, LH	Broken	12.00 FL	*12.00 FL
7	1		*GUARD ASSY-FRONT WHEEL, LH	Broken	75.00 FL	*75.00 FL
8	1		*PANEL-FENDER, LH	Dented	425.00 FL	*425.00 FL
9	1		*INSULATOR-FENDER LH	Not Necessary	48.00 FL	*- FL
10	1		*LAMP ASSY-HEAD, LH	Not Necessary	1,558.00 FL	*- FL
11	1		*PANEL ASSY-FRONT DOOR, LH	Dented	1,097.00 FL	*1,097.00 FL
12	1		*PANEL ASSY-REAR DOOR, LH	Dented	977.00 FL	*977.00 FL
13	1		*BLACK TAPE-FRT DOOR FRAME UPR	Necessary	13.00 FL	*13.00 FL
14	1		*TAPE-FR DR BLACK FRAME RR LH	Necessary	14.00 FL	*14.00 FL
15	1		*TAPE-FR DR BLACK FRAME FR, LH	Necessary	11.00 FL	*11.00 FL
16	1		*TAPE-RR DR BLACK FRAME UPR, LH	Necessary	12.00 FL	*12.00 FL
17	1		*TAPE-RR DR BLACK RR, LH	Necessary	9.00 FL	*9.00 FL
18	1		*PANEL-SIDE SILL OUTRER, LH	Repair	1,612.00 FL	*- FL
19	1		*CROSSMEMBER COMPL-FR AXLE	Not Necessary	1,190.00 FL	*- FL
20	1		*ARM COMPLETE-FR LWR, LH	Bent	429.00 FL	*429.00 FL
21	1		*GEAR ASSY-STEERING	Not Necessary	832.00 FL	*- FL
22	1		*BEARING-FRONT WHEEL HUB	Necessary	251.00 FL	*251.00 FL
23	1		*KNUCKLE-FRONT AXLE, LH	Bent	344.00 FL	*344.00 FL
24	1		*STRUT ASSY-FR, LH	Bent	335.00 FL	*335.00 FL
25	1		*BUMPER-RUBBER	Necessary	42.00 FL	*42.00 FL
26	1		*BEARING-STRUT	Bent	53.00 FL	*53.00 FL
27	1		*PAD-FRONT SPRING, UPR	Not Necessary	47.00 FL	*- FL
28	1		*INSULATOR ASSY-STRUT	Necessary	104.00 FL	*104.00 FL
29	1		*LINK ASSY-FRONT STABILIZER, LH	Bent	94.00 FL	*94.00 FL
30	1		*BAR ASSY-FR STABILIZER	Not Necessary	274.00 FL	*- FL
31	1		*END ASSY-TIE ROD,LH	Bent	61.00 FL	*61.00 FL
32	1		*SENSOR ASSY-ABS FRONT WHEEL,L	Torn	137.00 FL	*137.00 FL
33	4		*HOLDER-PARKING ASSIST SYSTEM	Necessary	68.00 FL	*68.00 FL
34	1		*FILM-ANTI CHIPPG LH	Necessary	13.00 FL	*13.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	11,644.00	5,867.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,184.00	1,069.40
- Nett Item Discount on N Items 20.00/0.00% (\$\$)	140.80	0.00
Total Parts (\$\$)	9,319.20	4,797.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER, FRT FENDER LH, FRT DOOR LH, REAR DOOR LH SIDE SILL LH	New	4,000.00	2,000.00
2	SPRAY PAINT FOR FRT BUMPER, FRT FENDER LH, FRT DOOR LH, REAR DOOR LH SIDE SILL LH	New	2,100.00	1,750.00
3	REMOVE & INSTALL FRT DOOR TRIMS AND GLASS	New	160.00	160.00
4	REMOVE & INSTALL REAR DOOR TRIMS AND GLASS	New	160.00	160.00
5	APPLY SEALANT FOR ACCIDENT PORTION	New	120.00	80.00
6	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
7	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
8	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
9	RENEW FRT UNDERCARRIAGE	New	400.00	400.00
10	TRANSFER FRT LEFT TYRE	New	30.00	30.00
11	SUPPLY FRT LEFT TYRE	New	460.00	0.00
Gross Labour Cost (S\$)			7,700.00	4,850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >