

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21000411/ETD3E2

Date: 02/02/2021

REFERENCE

Insured/Claimant:	LIM CHONG HUNG	Policy No:	1700045488		
Date of Loss:	08/01/2021	Nature of Claim:	OD	Claim No:	6348323922SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR8563C		
Make & Model:	KIA SORENTO, 2.2 (A)	Engine No:	D4HBHH327437
Reg. Date:	30/08/2017 (Man. Year: 2017)	Chassis No:	KNAPH81BSH5376777
Colour:	White	Odometer:	85062 km
Engine Capacity:	2199 cc		
Market Value/New Car Price:	S\$98,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Hankook 5 mm	Rear Left Side:	Hankook 5 mm
Front Right Side:	Hankook 5 mm	Rear Right Side:	Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,189.00	3,310.80	3,878.20	53.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,150.00	1,750.00	400.00	18.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,339.00	5,060.80	4,278.20	45.81
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	9,039.00	4,760.80	4,278.20	47.33
+ GST 7.00/7.00% (S\$)	632.73	333.26	299.47	47.33
Nett Amount (S\$)	9,671.73	5,094.06	4,577.67	47.33

INSPECTION

Date of Assignment:	11/01/2021		
Date Inspected:	11/01/2021	Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	4.0 days		

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE WITH FRAME	Necessary	50.00 FS	*50.00 FS
2	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
3	1		*COVER-FR BUMPER UPR	Dented	645.00 F	*645.00 FL
4	1		*COVER-FR BUMPER, LWR	Broken	645.00 F	*645.00 FL
5	1		*BRACKET-FR BPR SIDE REINF, RH	Not Necessary	22.00 F	*- FL
6	1		*GRILLE-FRONT BUMPER	Cut	178.00 F	*178.00 FL
7	1		*ABSORBER-FRONT BUMPER ENERGY	Broken	134.00 F	*134.00 FL
8	1		*GRILLE ASSY-RADIATOR	Cracked	738.00 F	*738.00 FL
9	1		*MOUNTING ASSY-LICENCE PLATE	Broken	37.00 F	*37.00 FL
10	1		*BRACKET-FR BUMPER SIDE, RH	Not Necessary	17.00 F	*- FL
11	1		*GRILLE-FRONT BUMPER FOG LAMP, R	Not Necessary	81.00 F	*- FL
12	1		*ULTRASONIC SENSOR ASSY-BWS	Not Necessary	187.00 F	*- FL
13	1		*PANEL ASSY-HOOD	Dented	1,654.00 F	*1,654.00 FL
14	1		*LAMP ASSY-HEAD, RH	Not Necessary	2,210.00 F	*- FL
15	1		*BEAM COMPLETE-FR BUMPER	Not Necessary	551.00 F	*- FL
16	10		*CLIPS (Supplementary)	Necessary	20.00 F	*20.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,189.00	4,121.00
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	810.20
Total Parts (S\$)	7,189.00	3,310.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER, BONNET	New	1,200.00	800.00
2	SPRAY PAINT FOR FRT BUMPER, BONNET	New	700.00	700.00
3	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
4	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
5	REMOVE & INSTALL PARKING SENSOR	New	60.00	60.00
6	APPLY SEALANT FOR ACCIDENT PORTION	New	40.00	40.00
Gross Labour Cost (\$\$)			2,150.00	1,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >