



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info |
|---|--|
| Mr Lim Chong Hung BLK 288C JURONG EAST ST 21 #08-400 SINGAPORE 603288 Contact No Mobile: 97317080 | Cust No/Name /Mr Lim Chong Hung Reg No/Reg Date SLR8563C / 30/08/201 Date In/Mileage / 0 Chassis No KNAPH81BSH5376777 Engine No D4HBHH327437 Make/Model KIA/SORENTO 2.2 A D GT SR 4WD CBF Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | | | |
|--|--------|-------------------|-----|--------------|--------|----------------|----------------|---------|
| CSM00081 | Cash | 09/01/2021/ 10:51 | Bod | 442 / CocoLu | 27049 | | | |
| Description of Goods / Services | | | | | Qty | Unit Price | Disc% | Amount |
| E PNT88000 | | | | | 800 | 600 | 800 | 1200.00 |
| RENEW FRT BUMPER, BONNET, | | | | | | | | 700.00 |
| E PNT98000 | | | | | | | | 50.00 |
| SPRAY PAINT FOR FRT BUMPER, BONNET | | | | | | | | 30.00 |
| M SUNDRY | | | | | | | | 120.00 |
| FRT NUMBER PLATE WITH FRAME | | | | | | | | 60.00 |
| A 90000001 | | | | | | | | 40.00 |
| CHECK WIRING & ELECTRICAL SYSTEM | | | | | | | | 20.00 |
| A 10028901 | | | | | | | | |
| TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST | | | | | | | | |
| USING HI-SCAN PRO TEST | | | | | | | | |
| E PNT88000 | | | | | | | | |
| REMOVE & INSTALL PARKING SENSOR | | | | | | | | |
| M SUNDRY | | | | | | | | |
| APPLY SEALANT FOR ACCIDENT PORTION | | | | | | | | |
| M SUNDRY | | | | | | | | |
| Sundry | | | | | 1.00 | 645.00 | 00.00 | 645.00 |
| M COVER-FR BUMPER UPR | 00 | | | | 1.00 | 645.00 | 00.00 | 645.00 |
| M COVER-FR BUMPER, LWR | BR | | | | 1.00 | 22.00 | 00.00 | 22.00 |
| M BRACKET-FR BPR SIDE REINF, RH | 1 X NM | | | | 1.00 | 178.00 | 00.00 | 178.00 |
| M GRILLE-FRONT BUMPER | CUT | | | | 1.00 | 134.00 | 00.00 | 134.00 |
| M ABSORBER-FRONT BUMPER ENERGY | 1 - BR | | | | 1.00 | 738.00 | 00.00 | 738.00 |
| M GRILLE ASSY-RADIATOR | CRA | | | | 1.00 | 37.00 | 00.00 | 37.00 |
| M MOUNTING ASSY-LICENCE PLATE | BR | | | | 1.00 | 17.00 | 00.00 | 17.00 |
| M BRACKET-FR BUMPER SIDE, RH | 1 X NM | | | | 1.00 | 81.00 | 00.00 | 81.00 |
| M GRILLE-FRONT BUMPER FOG LAMP, R | 1 X NM | | | | 1.00 | 187.00 | 00.00 | 187.00 |
| M ULTRASONIC SENSOR ASSY-BWS | 1 X NM | | | | 1.00 | 1654.00 | 00.00 | 1654.00 |
| M PANEL ASSY-HOOD | 00 | | | | 1.00 | 2210.00 | 00.00 | 2210.00 |
| M LAMP ASSY-HEAD, RH | 1 X NM | | | | 1.00 | 551.00 | 00.00 | 551.00 |
| M BEAM COMPLETE-FR BUMPER | 1 X NM | | | | | | | |

Estimate

Stev CLKK)

00- Nol AL

EXCIS -?

11/1/21, S. Anger

P/P

Estimate

Steve CLKK)
00- NOL AL
EXCISE - ?
11/1/21, 5.00pm
P/P

Confirm & accepted by

Ry BL SM
4 days

7% GST on
Total Payable

Nett
9,319.00
652.33

9,971.33

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.