

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21000422/AGS3Q2
Date: 25/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100462086
Claimant Vehicle No :	SGV1082H	Insured Vehicle No :	SLB7473U
Date of Loss:	08/01/2021	Nature of Claim:	TP
		Claim No:	7824893667SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGV1082H		
Make & Model:	KIA CERATO, 1.6 EX (A)	Engine No:	G4FGJH709060
Reg. Date:	15/11/2018 (Man. Year: 2018)	Chassis No:	KNAF3416MK5017923
Colour:	Black	Odometer:	32417 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,938.81	3,490.11	1,448.70	29.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,040.00	1,320.00	720.00	35.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,978.81	4,810.11	2,168.70	31.08
Approved Total (Overridden) (S\$)		3,800.00		

(S\$)	6,978.81	3,800.00	3,178.81	45.55
Nett Amount (S\$)	7,467.33	4,066.00	3,401.33	45.55
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,773.45		

INSPECTION

Date of Assignment: 11/01/2021

Date Inspected: 11/01/2021

Inspected At:

RYDER AUTO PTE LTD
2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB
SINGAPORE 417921

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	825.60 FL	*688.00 FL
2	10		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
3	1		*REAR END PANEL	Repair	349.92 FL	*- FL
4	1		*REAR END PANEL INNER TRIM	Deformed	54.00 FL	*54.00 FL
5	1		*REAR BUMPER ENFORCEMENT	Cracked	343.32 FL	*343.32 FL
6	2		*REAR BUMPER O/S & N/S RETAINER	Necessary	92.40 FL	*92.40 FL
7	1		*REAR BUMPER LOWER DIFFUSER	Deformed	260.52 FL	*260.52 FL
8	4		*REAR BUMPER REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
9	1		*REAR BOOT COVER	Dented	1,557.24 FL	*954.00 FL
10	1		*REAR BOOT COVER WEATHERSTRIP	Not Necessary	110.00 FL	*- FL
11	1		*REAR BOOT COVER EMBLEM	Necessary	52.30 FL	*52.30 FL
12	1		*REAR BOOT COVER CERATO EMBLEM	Necessary	42.40 FL	*42.40 FL
13	1		*REAR BOOT COVER C&C EMBLEM	Necessary	51.20 FL	*51.20 FL
14	1		*REAR BOOT COVER LOCK (UPPER)	Damaged	82.40 FL	*82.40 FL
15	1		*REAR TAILLAMP N/S	Cracked	609.00 FL	*609.00 FL
16	1		*REAR O/S & N/S FOG LAMP	N/S Cracked	434.40 FL	*217.20 FL
17	1		*REAR O/S & N/S FOG LAMP GARNISH	N/S Deformed	161.20 FL	*80.60 FL
18	1		*REAR N/S TAIL LAMP (NPA)	Cracked	0.00 FL	*- FL
19	1		*REAR N/S STAY	Bent	95.00 FL	*95.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,450.90	3,852.34
- List Item Discount on L Items 10.00/10.00% (\$)	512.09	362.23
Total Parts (\$)	4,938.81	3,490.11

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE REAR DAMAGED PARTS ,STRAIGHTEN & WELDING	New	1,000.00	600.00
2	TO SPRAY PAINTING	New	800.00	600.00
3	TO REMOVE AND REPLACE REAR REVERSE SENSOR	New	80.00	50.00
4	TO CHECK WIRING	New	80.00	30.00
5	TO RE-SEAL ANTI-RUST	New	80.00	40.00
Gross Labour Cost (S\$)			2,040.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >