

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21000425/T1QD3Q2

Date: 01/02/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001471242

Claimant

Vehicle No : SH7727Z

Insured Vehicle No : SLU2619A

Date of Loss: 09/01/2021

Nature of Claim: TP

Claim No: 251878

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SH7727Z**

Make & Model: HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)

Engine No: D4FDGU614103

Reg. Date: 05/05/2016 (Man. Year: 2016)

Chassis No: KMHLB41UMGU087919

Colour: Blue

Odometer: 578419 km

Engine Capacity: 1685 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size:

205/60 R16

Front Left Side: West Lake 6 mm

Rear Left Side:

West Lake 6 mm

Front Right Side: West Lake 6 mm

Rear Right Side:

West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,374.38	6,641.10	2,733.28	29.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,680.00	1,680.00	1,000.00	37.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,054.38	8,321.10	3,733.28	30.97
Approved Total (Overridden) (S\$)		6,600.00		
(S\$)	12,054.38	6,600.00	5,454.38	45.25
+ GST 7.00/7.00% (S\$)	843.81	462.00	381.81	45.25
Nett Amount (S\$)	12,898.19	7,062.00	5,836.19	45.25

INSPECTION

Date of Assignment: 11/01/2021

Date Inspected: 11/01/2021 Inspected At:

ComfortDelGro Engineering Pte Ltd
(Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Feb 2021)
Parts:	143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SH7727Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BOOTLID	Bent	2,174.90 FL	*2,174.90 FL
2	2	*BOOTLID HINGE (LH/RH)	Repair	284.60 FL	*- FL
3	1	*BOOTLID LOCK UPPER	Bent	114.90 FL	*114.90 FL
4	1	*BOOTLID LOCK LOWER	Repair	31.70 FL	*- FL
5	1	*BOOTLID HYUNDAI PLATE	Necessary	21.10 FL	*21.10 FL
6	1	*BOOTLID H EMBLEM	Necessary	63.10 FL	*63.10 FL
7	1	*BOOTLID CRDI PLATE	Necessary	52.40 FL	*52.40 FL
8	2	*BOOTLID LAMP (LH/RH)	Not Necessary	1,131.20 FL	*- FL
9	1	*BOOTLID TRIMBOARD	Torn	343.90 FL	*343.90 FL
10	11	*BOOTLID TRIMBOARD CLIPS	Necessary	11.00 FL	*11.00 FL
11	1	*BOOTLID MOULDING (I40)	Cut	85.00 FL	*85.00 FL
12	1	*BOOTLID I40 EMBLEM (I40)	Necessary	67.90 FL	*67.90 FL
13	1	*BOOTLID LOWER GARNISH (I40)	Deformed	227.90 FL	*227.90 FL
14	1	*REAR BUMPER	Deformed	1,106.00 FL	*1,106.00 FL
15	2	*REAR BUMPER REINFORCEMENT BRACKET LH/RH	Not Necessary	321.20 FL	*- FL
16	1	*REAR BUMPER REINFORCEMENT	Cracked	428.40 FL	*428.40 FL
17	10	*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
18	2	*REAR BUMPER SIDE RETAINER RH/LH	Deformed	71.20 FL	*71.20 FL
19	1	*REAR BUMPER SPONGE	Cracked	119.50 FL	*119.50 FL
20	1	*REAR BUMPER UNDER COVER	Not Necessary	228.00 FL	*- FL
21	1	*REAR BUMPER REFLECTOR LH/RH	N/S Cut	64.00 FL	*32.00 FL
22	1	*TAIL LAMP (LH/RH)	N/S Cracked	1,395.60 FL	*697.80 FL
23	1	*REAR END PANEL	Bent	526.70 FL	*526.70 FL
24	1	*REAR END PANEL GARNISH	Deformed	57.70 FL	*57.70 FL
25	1	*REAR END PANEL LOWER PANEL	Repair	495.50 FL	*- FL
26	1	*REAR TOWING HOOK	Not Necessary	194.60 FL	*- FL
27	1	*EXHAUST MUFFLER RH	Bent	967.70 FL	*967.70 FL
28	1	*EXHAUST CENTRE PIPE	Bent	730.10 FL	*730.10 FL
29	1	*SPARE TYRE FASTENER	Deformed	41.80 FL	*41.80 FL
30	1	*BOOTLID COMFORTDELGRO	Necessary	30.00 FS	*30.00 FS
31	1	*BOOTLID 65521111	Necessary	30.00 FS	*30.00 FS
32	1	*REAR NO.PLATE	Cut	25.00 FS	*25.00 FS
33	1	*REAR BUMPER MAT	Necessary	50.00 FS	*50.00 FS
34	1	*REVERSE SENSOR	Not Working	135.70 FS	*135.70 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,650.30	8,233.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,275.92	1,592.60
Total Parts (\$\$)	9,374.38	6,641.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,200.00	840.00
2	SPRAY PAINTING CHARGE	New	1,200.00	750.00
3	WIRING CHARGE	New	60.00	30.00
4	TUFF KOTE	New	100.00	30.00
5	REMOVE/REFIX REVERSE SENSOR	New	120.00	30.00
Gross Labour Cost (\$\$)			2,680.00	1,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >