

ASS. REC. BY:

REF:

1702/21004261K

Henneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 893K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLump Sum: 1-B-1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SL E5430R Yr Regn: 05 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or WagonMake: Volvo XC60 c.c. 1969Colour: M. Brown A/C: Insured / Std / NI / NASp. Reading: 23685 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: YV10840LDG 2847873Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NI / S/Rlm / STD / Rlm or

Tyre Size: Winn Force 235/60R18R: Davanti

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 9 mm R/Bal. 7 mmL/Bal. 9 mm L/Bal. 7 mmD.O.A. 17/12/20 D.O.I. 11/1/2021

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

015 151

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 / Est not ready3/2 / 41 Rm 856501

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trlp: _____

Survey Fee: _____

Transportation: _____

S + RS. SI

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Report Format :

Lump Sum / I.B.I: (\$ _____)

KUM CHEW MOTOR WORKSHOP

160, SIN MING DRIVE #05-08
 SIN MING AUTOCITY, SINGAPORE 575722.
 Tel No. : 64536256/64563715 Fax No. : 64557754
 E-Mail : kumchew1@singnet.com.sg
 GST Reg.No. : M90367665T Buss. Reg. No. : 52865130K

M/S FIRST CAPITAL INSURANCE LTD
 36, ROBINSON ROAD #16-01
 CITY HOUSE, SINGAPORE 068877.
 cwsmotorclaims@msfirstcapital.com.sg

Attention : Motor Claim Department

Contact : 62222311/65073848(C) 65073852 Fax No. : 62244174/65073849(C)

Estimate : ES005154

Date : 30/01/2021

Vehicle Num. : SLE 5430 R

Make/Model : VOLVO XC60

Chassis/Eng# :

Accident Date : 17/12/2020

Claim No. :

Reference : KC/TP5430/2101-01

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|-----|--------|---------------------------------|--|--|
| 1. | 1 PC | LIST ITEMS : | | |
| 2. | 1 PC | FRT HEADLAMP NOZZLE COVER - R/H | | |
| 3. | 1 PC | FRT HEADLAMP NOZZLE ARM - R/H | | |
| 4. | 1 PC | FRT BUMPER | | |
| 5. | 1 PC | FRT BUMPER SPONGE | | |
| 6. | 1 PC | FRT BUMPER REINFORCEMENT | | |
| 7. | 1 PC | FRT BUMPER TOW COVER | | |
| 8. | 18 PCS | FRT FENDER DUST COVER - RH | | |
| 9. | 1 PC | FRT FENDER DUST COVER CLIPS | | |
| 10. | 1 PC | FOG LAMP | | |
| 11. | 1 PC | POWER STEERING PUMP (CHECK) | | |
| 12. | 1 PC | HEADLAMP - R/H | | |
| 13. | 1 PC | NOZZLE COVER BRACKET - R/H | | |
| 14. | 1 PC | NOZZLE COVER PLATE | | |
| 15. | 1 PC | NOZZLE COVER | | |
| 16. | 1 PC | REAR BUMPER RETAINER - R/H | | |

List TotalS\$:

10.00% Discount S\$:

LABOUR :

TO PULL, KNOCK ON ACCIDENT PORTION & CHANGE ABOVE PART.

TO SPRAY & PAINT ON ACCIDENT PORTION.

nit	48.00	✓
nit	98.00	✓
cm	1,682.00	✓
sn	180.00	✓
sn	1,260.00	✓
nit	70.00	✓
cm	180.00	✓
sn	68.40	✓
nit	385.00	✓
cm	2,800.00	✓
cm	85.00	✓
sn	40.00	✓
sn	7.00	✓
dry	78.00	✓
	6,981.40	
	698.14	
	6,283.26	

3001

550.00

400 600.00

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

KUM CHEW MOTOR WORKSHOP

160, SIN MING DRIVE #05-08
 SIN MING AUTOCITY, SINGAPORE 575722.
 Tel No. : 64536256/64563715 Fax No. : 64557754
 E-Mail : kumchew1@singnet.com.sg
 GST Reg.No. : M90367665T Buss. Reg. No. : 52865130K

M/S FIRST CAPITAL INSURANCE LTD
 36. ROBINSON ROAD #16-01
 CITY HOUSE, SINGAPORE 068877.
 cwsmotorclaims@msfirstcapital.com.sg

Attention : Motor Claim Department

Contact : 62222311/65073848(C) 65073852 Fax No. : 62244174/65073849(C)

Estimate : ES005154

Date : 30/01/2021
 Vehicle Num. : SLE 5430 R
 Make/Model : VOLVO XC60
 Chassis/Eng# :
 Accident Date : 17/12/2020
 Claim No. :
 Reference : KC/TP5430/2101-01
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO CHECK HEADLAMP FUNCTIONS.		60.00
		Labour Total S\$:		1,210.00

SingDollars : Seven Thousand Four Hundred Ninety-Three & Cents Twenty-Six Only

Total S\$: 7,493.26

KUM CHEW MOTOR WORKSHOP