

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21000429/AVF3Q2

Date: 28/01/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00105812000
Claimant Vehicle No :	JJN5490	Insured Vehicle No :	GBG8690U
Date of Loss:	05/01/2021	Nature of Claim:	TP
		Claim No:	SNM21D200106/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	JJN5490		
Make & Model:	NISSAN VANETTE, 1.5 C22 (M)	Engine No:	A15C079783
Reg. Date:	26/01/2006 (Man. Year: 2005)	Chassis No:	PN8VPC22JTCA49793
Colour:	Silver	Odometer:	229625 km
Engine Capacity:	1488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/70R13	Rear Tyre Size:	175/70R13
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,194.44	3,602.49	1,591.95	30.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,030.00	1,700.00	330.00	16.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,224.44	5,302.49	1,921.95	26.60
Approved Total (Overridden) (\$\$)		3,000.00		
(\$\$)	7,224.44	3,000.00	4,224.44	58.47
+ GST 7.00/7.00% (\$\$)	505.71	210.00	295.71	58.47
Nett Amount (\$\$)	7,730.15	3,210.00	4,520.15	58.47

INSPECTION

Date of Assignment: 11/01/2021

Date Inspected: 12/01/2021 Inspected At:

Ryder Auto Pte Ltd (HQ)
2 Kaki Bukit Ave 2, #02-19 AutoHub
@ Kaki Bukit
Singapore 417921

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 28 Jan 2021)	
Parts:	N/A	NISSAN VANETTE 1.5 C22 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for JJN5490)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	681.40 FN	*461.00 FN
2	1		*REAR BUMPER ENFORCEMENT	Bent	451.40 FN	*298.00 FN
3	2		*REAR BUMPER O/S & N/S REFLECTOR	Not Necessary	475.40 FN	*- FN
4	2		*REAR BUMPER O/S & N/S RETAINER	Necessary	12.70 FN	*12.70 FN
5	1		*REAR END PANEL	Dented	481.90 FN	*481.90 FN
6	2		*REAR O/S & N/S TAIL-LAMP	Cracked	878.20 FN	*592.00 FN
7	1		*REAR TAIL GATE	Distorted	1,174.40 FN	*1,174.40 FN
8	1		*REAR TAIL GATE WEATHERSTRIP	Not Necessary	174.40 FN	*- FN
9	1		*REAR TAIL GATE LOWER MOULDING (BLACK)	Deformed	187.10 FN	*187.10 FN
10	1		*REAR TAIL GATE LOCK (UPPER)	Damaged	291.60 FN	*209.00 FN
11	1		*REAR TAIL GATE LOCK (LOWER)	Not Necessary	43.10 FN	*- FN
12	1		*REAR SPARE WHEEL BRACKET	Bent	220.00 FN	*220.00 FN
13	10		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
14	2		*REAR BUMPER SCREW CLIPS	Necessary	20.00 FS	*20.00 FS
15	2		*REAR REVERSE SENSOR	Damaged	380.00 FS	*200.00 FS
16	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
17	1		*REAR WINDSCREEN INNER SEAL	Necessary	120.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	5,701.60	3,966.10
- Nett Item Discount on N Items 10.00/10.00% (S\$)	507.16	363.61
Total Parts (S\$)	5,194.44	3,602.49

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE DAMAGED PARTS,STRAIGHTEN & WELDING	New	1,000.00	800.00
2	TO SPRAY PAINTING	New	800.00	700.00
3	TO REMOVE & REFIT REAR WINDSCREEN	New	130.00	120.00
4	TO CHECK WIRING	New	50.00	30.00
5	TO RE-SEAL ANTI-RUST	New	50.00	50.00
Gross Labour Cost (\$\$)			2,030.00	1,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >