



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBR 7765L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT FOOT REST L/H	CUT	185.00	68.00
1	FRONT FOOT REST BRACKET	BENT	360.00	105.00
1	SET FRONT FAIRING	CUT	1,750.00	1,020.00
1	SET FRONT FORK TUBE	NOT NECESSARY	740.00	-
1	FRONT FORK OILSEAL	NOT NECESSARY	80.00	-
1	FRONT FORK OIL	NOT NECESSARY	20.00	-
1	FRONT STEEM STEERING BEARING	NOT NECESSARY	185.00	-
1	FRONT HEAD LAMP	NOT NECESSARY	275.00	-
1	FRONT SPEEDO METER	NOT NECESSARY	2,450.00	-
1	FRONT MIRROR N/S	BROKEN	68.00	48.00
1	FRONT BRAKE LEVER	NOT NECESSARY	65.00	-
1	FRONT CLUTCH LEVER	SCRATCHED	65.00	62.00
1	FRONT HANDLE BAR N/S	BENT	180.00	175.00
1	SET FRONT HANDLE GRIP	NOT NECESSARY	30.00	-
1	SET FRONT HANDLE BAR BALANCER	CUT	35.00	28.00
1	THROTTLE CABLE	NOT NECESSARY	65.00	-
1	CRASH BAR	NOT FITTED	290.00	-
1	REAR SPORT RIM	TO REPAIR SEE LABOUR	1,200.00	-
1	REAR L/H DISC	NOT NECESSARY	350.00	-
1	REAR RIM SAP	NOT NECESSARY	75.00	-
1	REAR RIM BEARING	NOT NECESSARY	40.00	-
1	RADIATOR	NOT NECESSARY	780.00	-
1	RADIATOR FAN	NOT NECESSARY	185.00	-
1	RADIATOR SIDE COVER IN	NOT NECESSARY	80.00	-
1	RADIATOR SIDE COVER OUT	NOT NECESSARY	185.00	-
1	COOLENT	NOT NECESSARY	30.00	-
1	SIGNAL FRONT N/S	CUT	110.00	75.00
1	GEAR LEVEL	BENT	180.00	145.00
1	REAR FOOT REST R/H	NOT NECESSARY	75.00	-
1	REAR FOOT REST L/H	CUT	75.00	68.00

Report Ref No. CS/SMO21000437/Uqd3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BRAKE CALIPER	NOT NECESSARY	750.00	-
1	REAR TAILLAMP	BROKEN	650.00	188.00
1	REAR WHEEL TOP GARNISH	DISTORTED	250.00	205.00
1	SEAT	TORN	300.00	80.00
1	REAR SHOCK ABSORBER L/H	NOT NECESSARY	400.00	-
	LESS 10% DISCOUNT		-1,255.80	-226.70
			11,302.20	2,040.30
1	REAR NUMBER PLATE (SN)	BENT	30.00	10.00
	LESS 10% DISCOUNT		-3.00	-
			27.00	10.00
	<b>LABOUR</b>			
	TRANSPORTATION CHARGES.		100.00	35.00
	TO RESPRAY PAINTING AND ETC.		1,300.00	200.00
	TO CHECK FRONT AND REAR ELECTRICAL WIRING.	NOT NECESSARY	200.00	-
	TO PRESS REAR SPORT RIM AND FORK.	NOT NECESSARY	350.00	-
	TO REMOVE,REFIX AND REALIGN FRONT FORK.	NOT NECESSARY	450.00	-
	TO STRAIGHTEN,REPAIR AND REALIGN CHASSIS FRAME MEMBER.	NOT NECESSARY	1,000.00	-
	PANEL BEATING,CUT,WELD REMOVE AND REPLACE ABOVE PARTS.INCLUSIVE OF THE REPAIR OF REAR SPORT RIM.		1,200.00	300.00
			4,600.00	535.00
<b>GRAND TOTAL</b>			<b>15,929.20</b>	<b>2,585.30</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,050.00</b>

Report Ref No. CS/SMO21000437/Uqd3q2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.