

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21000439/EQD3E2

Date: 27/01/2021

REFERENCE

Insured/Claimant:	TAY CHEE YONG	Policy No:	1900156670		
Date of Loss:	11/01/2021	Nature of Claim:	OD	Claim No:	7535058293SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN9507T		
Make & Model:	KIA STONIC, 998cc (A)	Engine No:	G3LCKP027889
Reg. Date:	02/09/2019 (Man. Year: 2019)	Chassis No:	KNAD6811VK6297469
Colour:	Grey	Odometer:	19286 km
Engine Capacity:	998 cc		
Market Value/New Car Price:	S\$77,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Kumho 4 mm	Rear Left Side:	Kumho 4 mm
Front Right Side:	Kumho 4 mm	Rear Right Side:	Kumho 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,614.00	4,207.20	7,406.80	63.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,880.00	3,690.00	3,190.00	46.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,494.00	7,897.20	10,596.80	57.30
+ GST 7.00/7.00% (S\$)	1,294.58	552.80	741.78	57.30
Nett Amount (S\$)	19,788.58	8,450.00	11,338.58	57.30

INSPECTION

Date of Assignment:	11/01/2021		
Date Inspected:	11/01/2021	Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	7.0 days		

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE FRAME	Necessary	50.00 FS	*50.00 FS
2	1		*REAR NUMBER PLATE	Necessary	50.00 FS	*50.00 FS
3	1		*C&C LOGO	Necessary	40.00 FS	*40.00 FS
4	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
5	1		*COVER-FR BUMPER, UPR	Broken	476.00 F	*476.00 FL
6	1		*COVER-FR BUMPER, LWR	Not Necessary	367.00 F	*- FL
7	1		*GRILLE-FRONT BUMPER	Broken	96.00 F	*96.00 FL
8	1		*SKID PLATE-FR BUMPER	Not Necessary	55.00 F	*- FL
9	1		*GRILLE ASSY-RADIATOR	Not Necessary	324.00 F	*- FL
10	1		*MOULDING-FRONT BUMPER A/INTAKE	Broken	61.00 F	*61.00 FL
11	1		*ABSORBER-FRONT BUMPER ENERGY	Broken	98.00 F	*98.00 FL
12	1		*STIFFNER-FR BPR LWR	Not Necessary	123.00 F	*- FL
13	1		*BRACKET-FR BUMPER SIDE, RH	Not Necessary	13.00 F	*- FL
14	1		*BRACKET-FR BUMPER SIDE, LH	Not Necessary	13.00 F	*- FL
15	1		*BEAM COMPLETE-FR BUMPER	Dented	544.00 F	*544.00 FL
16	1		*ORNAMENT-KIA NO.115	Not Necessary	32.00 F	*- FL
17	1		*LOGO ASSY-KIA SUB	Necessary	51.00 F	*51.00 FL
18	1		*EMBLEM - STONIC	Necessary	26.00 F	*26.00 FL
19	1		*EMBLEM - TURBO G.D.I	Necessary	38.00 F	*38.00 FL
20	1		*LAMP ASSY-HEAD, RH	Not Necessary	1,845.00 F	*- FL
21	1		*LAMP ASSY-HEAD, LH	Not Necessary	1,845.00 F	*- FL
22	1		*COVER-RR BUMPER LWR	Broken	366.00 F	*366.00 FL
23	1		*SKID PLATE-RR BUMPER	Broken	122.00 F	*122.00 FL
24	1		*MOULDING ASSY-RR BUMPER SIDE, R	Not Necessary	152.00 F	*- FL
25	1		*MOULDING ASSY-RR BUMPER SIDE, L	Dented	152.00 F	*152.00 FL
26	1		*LAMP ASSY-REAR FOG & R/REFL, RH	Not Necessary	111.00 F	*- FL
27	1		*LAMP ASSY-REAR FOG & R/REFL, LH	Not Necessary	111.00 F	*- FL
28	1		*COVER-RR BUMPER SIDE UNDER	Broken	62.00 F	*62.00 FL
29	1		*WIRING HARNESS-BWS EXT	Not Necessary	245.00 F	*- FL
30	2		*BRACKET-RR BEAM UPR MTG	Not Necessary	14.00 F	*- FL
31	1		*BRACKET-RR BEAM LWR MTG, RH	Not Necessary	5.00 F	*- FL
32	1		*BRACKET-RR BEAM LWR MTG, LH	Not Necessary	7.00 F	*- FL
33	1		*ANTENNA ASSY-SMARTKEY	Not Necessary	32.00 F	*- FL
34	1		*STAY-RR BUMPER RH	Bent	55.00 F	*55.00 FL
35	1		*STAY-RR BUMPER LH	Bent	55.00 F	*55.00 FL
36	1		*BEAM-RR BUMPER	Broken	419.00 F	*419.00 FL
37	2		*ULTRASONIC SENSOR ASSY-BWS	Not Necessary	378.00 F	*- FL
38	2		*ULTRASONIC SENSOR ASSY-BWS	Not Necessary	378.00 F	*- FL
39	1		*PANEL ASSY-BACK	Repair	345.00 F	*- FL
40	1		*MUFFLER ASSY-REAR	Dented	665.00 F	*665.00 FL
41	1		*MUFFLER ASSY-REAR	Bent	362.00 F	*362.00 FL
42	1		*RR CAMERA & TRUNK LID HDL ASSY	Cut	758.00 F	*758.00 FL
43	1		*CAP-RR HOOK (Supplementary)	Crushed	5.00 F	*5.00 FL
44	1		*CONDENSER ASSY-COOLER (Supplementary)	Bent	648.00 F	*648.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,614.00	5,219.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	1,011.80
Total Parts (\$\$)	11,614.00	4,207.20

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER	New	800.00	400.00
2	SPRAY PAINT FOR FRT BUMPER	New	700.00	350.00
3	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
4	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
5	RENEW REAR BUMPER, REAR END PANEL, REPAIR TAILGATE	New	1,600.00	400.00
6	REMOVE & INSTALL PARKING SENSOR	New	60.00	60.00
7	SPRAY PAINT FOR REAR BUMPER, REAR END PANEL, BOOTLID	New	1,600.00	700.00
8	REMOVE & INSTALL REAR COMPARTMENT TRIMS	New	300.00	0.00
9	RENEW REAR EXHAUST SYSTEM	New	400.00	400.00
10	RENEW REAR CAMERA	New	300.00	300.00
11	APPLY SEALANT FOR ACCIDENT PORTION	New	40.00	0.00
12	VACUUM & TOP UP A/COND GAS (Supplementary)	New	80.00	80.00
13	REMOVE & REPLACE A/COND CONDENSER (Supplementary)	New	100.00	100.00
14	REPAIR REAR END PANEL (Supplementary)	New	400.00	400.00
15	RESPRAY ON REAR END PANEL (Supplementary)	New	350.00	350.00
Gross Labour Cost (\$\$)			6,880.00	3,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >