

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG21000440/EVF3E2

**Date:** 25/01/2021

### REFERENCE

Insured/Claimant:	NG BEE HOON	Policy No:	1700021056-03	Claim No:	0694606268SG
Date of Loss:	09/01/2021	Nature of Claim:	OD		

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFM9300K	Engine No:	G4LEHS158528
Make & Model:	KIA NIRO, 1.6 HYBRID GDI DCT SUNROOF (A)	Chassis No:	KNACC81CVH5087831
Reg. Date:	30/06/2017 (Man. Year: 2017)	Odometer:	47041 km
Colour:	Brown		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	S\$72,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,886.00	1,388.00	498.00	26.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,260.00	2,110.00	1,150.00	35.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,146.00</b>	<b>3,498.00</b>	<b>1,648.00</b>	<b>32.02</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>360.22</b>	<b>244.86</b>	<b>115.36</b>	<b>32.02</b>
<b>Nett Amount (S\$)</b>	<b>5,506.22</b>	<b>3,742.86</b>	<b>1,763.36</b>	<b>32.02</b>

### INSPECTION

Date of Assignment:	11/01/2021		
Date Inspected:	11/01/2021	Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	5.0 days		

**Adjuster:** CHEN TSUE YEE

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*C&C LOGO	Necessary	40.00 FS	*40.00 FS
2	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
3	1		*COVER-RR BUMPER, UPR	Broken	486.00 F	*486.00 FL
4	1		*COVER-RR BUMPER LWR	Cut	392.00 F	*392.00 FL
5	1		*SKID PLATE-RR BUMPER	Cut	122.00 F	*122.00 FL
6	1		*COVER-RR BUMPER SIDE UNDER, LH	Not Necessary	27.00 F	*- FL
7	1		*PIECE-RR BUMPER SIDE, LH	Broken	16.00 F	*16.00 FL
8	1		*PIECE-RR BUMPER SIDE, RH	Cracked	16.00 F	*16.00 FL
9	1		*COVER-RR BUMPER SIDE UNDER, RH	Not Necessary	27.00 F	*- FL
10	1		*MOULDING ASSY-RR BUMPER SIDE, R	Not Necessary	20.00 F	*- FL
11	1		*MOULDING ASSY-RR BUMPER SIDE, L	Not Necessary	20.00 F	*- FL
12	1		*REFLECTOR / REFLEX ASSY-RR LH	Broken	104.00 F	*104.00 FL
13	1		*LAMP ASSY-LICENSE PLATE, LH	Not Necessary	27.00 F	*- FL
14	1		*LAMP ASSY-LICENSE PLATE, RH	Not Necessary	27.00 F	*- FL
15	1		*BRACKET-RR RAIL LWR MTG	Not Necessary	6.00 F	*- FL
16	1		*BEAM-RR BUMPER	Broken	261.00 F	*261.00 FL
17	1		*BRACKET-RR RAIL LWR MTG	Not Necessary	6.00 F	*- FL
18	1		*STAY-RR BUMPER LH	Bent	67.00 F	*67.00 FL
19	1		*BRACKET-RR BEAM UPR MTG, LH	Not Necessary	6.00 F	*- FL
20	1		*EMBLEM-NIRO	Necessary	25.00 F	*25.00 FL
21	1		*LOGO-KIA	Necessary	42.00 F	*42.00 FL
22	1		*EMBLEM-ECO HYBRID	Necessary	29.00 F	*29.00 FL
23	1		*STAY-RR BUMPER RH (Supplementary)	Bent	67.00 F	*67.00 FL
24	1		*CAP-R HOOK (Supplementary)	Crushed	8.00 F	*8.00 FL
25	1		*BRACKET ASSY-RR BUMPER SIDE,LH (Supplementary)	Broken	25.00 F	*25.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,886.00	1,720.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	332.00
Total Parts (\$\$)	1,886.00	1,388.00

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	RENEW REAR BUMPER, REPAIR TAILGATE, REAR END PANEL	New	1,200.00	400.00
2	REMOVE & INSTALL PARKING SENSOR	New	60.00	60.00
3	SPRAY PAINTN FOR REAR BUMPER, TAILGATE, REAR END PANEL	New	1,050.00	700.00
4	APPLY REAR NUMBER PLATE WITH FRAME	New	50.00	50.00
5	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	REPAIR ON REAR END PANEL (Supplementary)	New	400.00	400.00
8	RESPRAY ON REAR END PANEL (Supplementary)	New	350.00	350.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,260.00</b>	<b>2,110.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >