



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMU 1881C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BONNET	DENTED	2,452.30	2,452.30
1	BONNET INNER RUBBER STRIP	ABRADED	185.10	185.10
1	FRONT RADIATOR GRILLE ASSY	CRACKED	799.60	799.60
1	FRONT RADIATOR GRILLE CHROME STRIP	DAMAGED	158.00	158.00
1	FRONT RADIATOR GRILLE ASSY LOGO	NECESSARY	102.00	102.00
1	FRONT SUPPORT PANEL TOP GARNISH	CRACKED	320.70	320.70
	LESS 10% DISCOUNT		-401.77	-401.77
			3,615.93	3,615.93
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET FRONT RADIATOR GRILLE CLIPS (SN)	NECESSARY	20.00	20.00
1	COATING (SN)	SERVICEABLE	700.00	-
			720.00	20.00
	<b><u>LABOUR</u></b>			
	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE 'PARTS REPAIR' COLUMN INCLUSIVE OF REPLACEMENT PARTS.		585.00	400.00
	PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIAL.		550.00	400.00
	APPLY RUST PROOFING ON THE ADJACENT PANELS.	NOT NECESSARY	20.00	-
	WIRING AND BULB CHECKING.	NOT NECESSARY	22.50	-
			1,177.50	800.00
	<b>GRAND TOTAL</b>		<b>5,513.43</b>	<b>4,435.93</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>3,550.00</b>

Report Ref No. CS3/LPC20013089/Gvd3e2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.