



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC20013089/Gvd3e2-1 Date: 21/01/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YN 2115U	Veh. Inspected	SMU 1881C
	Policy No.		Coverage (\$)	0.00
	Claim No.	20/20/20/VC00/023927	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	09/01/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA LEXUS IS300	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	JTHBA1D2005101953	Colour	BLACK
	Odometer	14287 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/45 R17	BRIDGESTONE	9 mm
	L/H Front Tyre	225/45 R17	BRIDGESTONE	9 mm
	R/H Rear Tyre	225/45 R17	BRIDGESTONE	9 mm
	L/H Rear Tyre	225/45 R17	BRIDGESTONE	9 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	19/11/2020	Inspection Date	01/12/2020
	Survey held at	ASSURE AUTO ASSIST PTE LTD 23 TUAS AVENUE 18 SINGAPORE 638902		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	