



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
 PANDAN GARDENS CUSTOMER SERVICE CENTRE  
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV13209/NG WEE WEE SOPHIA (HUANG HUIHUI)
	Reg No/Reg Date	SMV9916D / 29/10/202
	Date In/Mileage	/ 3894
	Chassis No	KNAF3416ML5069507
	Engine No	G4FGKH755599
	Make/Model	KIA/CERATO 1.6 A EX G333
Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	11/01/2021/ 13:49	QUD	247 / DonBong	27193

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON REAR BOOT LID, REAR BUMPER, REAR BODY KITS, CUT/WELD REAR END PANEL, REPAIR BOTH REAR FENDER	1			2000.00
E PNT88000 REMOVE AND INSTALL PARKING ASSISTANCE				60.00
E PNT88000 REMOVE AND INSTALL REAR CABIN TO FACILITATE REPAIR WORK				120.00
E PNT88000 REMOVE AND REPLACE REAR BODY KITS				80.00
E PNT98000 PAINT WORK SPRAY REAR FLOOR PANEL REAR END PANEL REAR BOOT LID, REAR BUMPER, REAR BODY KITS, RH REAR FENDER LH REAR FENDER AND AFFECTED PORTION				2800.00
M SUNDRY APPLY BODY SEALANT				120.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				30.00
M SUNDRY PERFORM RUST PEVENTION				120.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				40
M SUNDRY SUPPLY C&C LOGO				40.00
M SUNDRY SUPPLY REAR PARKING SENSOR				220.00
M SUNDRY SUNDRIES				20
M PANEL ASSY-BACK	1.00	324.00	20.00	259.20
M W/STRIP-TRUNK LID OPNG	1.00	100.00	20.00	80.00
M LATCH ASSY-TRUNK LID	1.00	112.00	20.00	89.60
M STRIKER ASSY-TRUNK LID	1.00	40.00	20.00	32.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Table with 2 main columns: Invoice Name & Address (AIG Asia Pacific Insurance Pte. Ltd.) and Owner Name & Vehicle Info (Cust No/Name, Reg No/Reg Date, Date In/Mileage, Chassis No, Engine No, Make/Model, Colour/Trim).

Main table with columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No, Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Includes handwritten notes and a large 'Estimate' watermark.

SURVEYOR NAME: Steve CLKK
SURVEYOR SIGNATURE: OD - Not Agt

DATE: 11/1/21, 4.30pm

Confirm & accepted by LK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis

Summary table with columns: Net (10,955.40), 7% GST on (766.88), Total Payable (11,722.28). Includes handwritten 'PIP' and '7 days'.

Authorized signatory and company stamp
Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.