LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/MSG20012866/R1TD3E2-1

Date:

13/01/2021

REFERENCE

Date of Loss:

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

Nature of Claim:

1001212937

Claimant Vehicle No

SGN8801X 07/11/2020

Insured Vehicle No:

SKU6934A

ΤP

Engine No:

Chassis No:

Odometer:

Claim No:

VF73ABHZTGJ643185

10JBHD3049789

42616 km

249584

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

Make & Model:

CITROEN GRAND C4 PICASSO, 1.6 BLUEHDI EAT6 (A)

21/07/2016 (Man. Year: 2016)

Reg. Date: Colour:

Brown

Engine Capacity:

1560 cc N/A

Market Value/New Car Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable): Pre-accident Condition:

Yes

Handbrake (Serviceable): **Engine Modification:** Yes

CONDITION OF TYRES

Front Tyre Size: Front Left Side: Front Right Side: 205/60 R15 Michelin 6 mm Michelin 6 mm

Rear Tyre Size: Rear Left Side: Rear Right Side:

Nο

205/60 R15 Michelin 6 mm

Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,422.00	2,797.00	625.00	18.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,000.00	910.00	1,090.00	54.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,422.00	3,707.00	1,715.00	31.63
Approved Total (Overridden) (S\$)		2,950.00		
(S\$)	5,422.00	2,950.00	2,472.00	45.59
+ GST 7.00/7.00% (S\$)	379.54	206.50	173.04	45.59
Nett Amount (S\$)	5,801.54	3,156.50	2,645.04	45.59

INSPECTION

Date of Assignment:

24/11/2020

Date Inspected:

24/11/2020 Inspected At:

Han Car Repairs (HQ)

BLK 1001 BUKIT MERAH LANE 3 #01-49 ALEXANDRA VILLAGE

Singapore 159718

Estimated Period of Repair: 4.0 days

MOHD RASUL Adjuster:

Manager:

DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 13 Jan 2021)

Parts: N/A CITROEN GRAND C4 PICASSO 1.6 BLUEHDI EAT6 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGN8801X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF

ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

	*FRONT N/S HEADLAMP	Damaged	705 00 EI	
		_ 41114904	705.00 FL	*705.00 FL
	*FRONT N/S SIGNAL LAMP	Damaged	225.00 FL	*225.00 FL
	*FRONT N/S FENDER	Damaged	560.00 FL	*560.00 FL
	*FRONT N/S FENDER INNER SHIELD	Damaged	190.00 FL	*190.00 FL
	*FRONT BUMPER	Damaged	1,120.00 FL	*1,120.00 FL
	*FRONT BUMPER REINFORCEMENT	Repair	500.00 FL	*-FL
	*FRONT BUMPER N/S SIDE RETAINER	Necessary	90.00 FL	*90.00 FL
	*FRONT BUMPER N/S FOG LAMP	Intact	130.00 FL	*-FL
	*FRONT BUMPER N/S FOG LAMP COVER	Damaged	140.00 FL	*140.00 FL
	*SET FRONT N/S FENDER INNER SHIELD CLIP	Necessary	48.00 FS	*30.00 FS
	*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*40.00 FS
hise part. S=SpcN	ett. L=ListItemDisc.	_		
		Sub Total (S\$)	3,788.00	3,100.00
	- List Item Discount on L Items	s 10.00/10.00% (S\$)	366.00	303.00
		Total Parts (S\$)	3,422.00	2,797.00
hi	se part. S=SpcNr	*FRONT BUMPER *FRONT BUMPER REINFORCEMENT *FRONT BUMPER N/S SIDE RETAINER *FRONT BUMPER N/S FOG LAMP *FRONT BUMPER N/S FOG LAMP COVER *SET FRONT N/S FENDER INNER SHIELD CLIP *SET FRONT BUMPER CLIP se part. S=SpcNett. L=ListItemDisc.	*FRONT N/S FENDER INNER SHIELD Damaged *FRONT BUMPER FRONT BUMPER REINFORCEMENT *FRONT BUMPER N/S SIDE RETAINER FRONT BUMPER N/S FOG LAMP Intact FRONT BUMPER N/S FOG LAMP COVER SET FRONT N/S FENDER INNER SHIELD CLIP SET FRONT BUMPER CLIP SET FRONT BUMPER CLIP SET FRONT BUMPER CLIP SET FRONT BUMPER CLIP SUB Total (S\$) - List Item Discount on L Items 10.00/10.00% (S\$)	*FRONT N/S FENDER INNER SHIELD Damaged 190.00 FL *FRONT BUMPER Damaged 1,120.00 FL *FRONT BUMPER REINFORCEMENT Repair 500.00 FL *FRONT BUMPER N/S SIDE RETAINER Necessary 90.00 FL *FRONT BUMPER N/S FOG LAMP Intact 130.00 FL *FRONT BUMPER N/S FOG LAMP COVER Damaged 140.00 FL *SET FRONT N/S FENDER INNER SHIELD CLIP Necessary 48.00 FS *SET FRONT BUMPER CLIP Necessary 80.00 FS se part. S=SpcNett. L=ListItemDisc. Sub Total (S\$) 3,788.00 - List Item Discount on L Items 10.00/10.00% (S\$) 366.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE AND REFIT REAR ELECTRICAL WIRING, REPLACED DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING	New	50.00	30.00
2	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE		900.00	400.00
3	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION	New	150.00	30.00
4	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WIELD BODY PANELS. TO READJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	900.00	450.00
	Gross Labour Cost (S\$)		2,000.00	910.00
	Report was unsubmitted during this print-out.	,		

< END OF ESTIMATES >