

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG21000475/ABA3Q2

**Date:** 18/03/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100423777

**Claimant**  
**Vehicle No :** SLX4578E **Insured Vehicle No :** SFU4020J

Date of Loss: 01/01/2021 Nature of Claim: TP Claim No: 9076719869SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                  |
|-----------------------------|-----------------------------------|-------------|------------------|
| Reg No:                     | SLX4578E                          |             |                  |
| Make & Model:               | HONDA CIVIC, 1.3 IMA CVT (A)      | Engine No:  | LDA24009453      |
| Reg. Date:                  | 27/11/2008 (Man. Year: 2008)      | Chassis No: | JHMF36209S201699 |
| Colour:                     | Silver                            | Odometer:   | 304279 km        |
| Engine Capacity:            | 1339 cc                           |             |                  |
| Market Value/New Car Price: | N/A                               |             |                  |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                  |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |              |                  |              |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size:  | 195/65 R15   | Rear Tyre Size:  | 195/65 R15   |
| Front Left Side:  | Firenza 6 mm | Rear Left Side:  | Firenza 6 mm |
| Front Right Side: | Firenza 6 mm | Rear Right Side: | Firenza 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                           | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                           | 9,030.90          | 6,386.96          | 2,643.94          | 29.28         |
| Miscellaneous Items                             | 0.00              | 0.00              | 0.00              |               |
| Labour                                          | 3,070.00          | 2,150.00          | 920.00            | 29.97         |
| Paintwork Labour                                | 0.00              | 0.00              | 0.00              |               |
| Towing                                          | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>             | <b>12,100.90</b>  | <b>8,536.96</b>   | <b>3,563.94</b>   | <b>29.45</b>  |
| <b>Approved Total (Overridden) (S\$)</b>        |                   | <b>6,800.00</b>   |                   |               |
| <b>Nett Amount (S\$)</b>                        | <b>12,100.90</b>  | <b>6,800.00</b>   | <b>5,300.90</b>   | <b>43.81</b>  |
| <b>+ Car Rental (6.0 x S\$110.00/day) (S\$)</b> |                   | 660.00            |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                   |                   | 2.00              |                   |               |
| <b>Nett Liability (S\$)</b>                     |                   | <b>7,462.00</b>   |                   |               |
| <b>Global Sum Settlement (S\$)</b>              |                   | <b>7,450.00</b>   |                   |               |

### INSPECTION

Date of Assignment: 04/01/2021

Date Inspected: 04/01/2021 Inspected At:

Cn Motors Pte Ltd (HQ)  
1 KAKI BUKIT AVENUE 6 BLK C #01-41  
AUTOBAY @ KAKI BUKIT  
Singapore 417883

Estimated Period of Repair: 7.0 days

**Adjuster:** ADRIAN LING**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                             | Condition     | Repairer's | Amount       |
|-----|-----|----------|-----------------------------------------|---------------|------------|--------------|
| 1   | 1   |          | *FRONT BONNET                           | Dented        | 581.30 F   | *581.30 FL   |
| 2   | 2   |          | *FRONT BONNET HINGE                     | Bent          | 64.00 F    | *64.00 FL    |
| 3   | 1   |          | *FRONT BONNET INSULATOR                 | Not Necessary | 187.60 F   | *- FL        |
| 4   | 10  |          | *FRONT BONNET INSULATOR CLIPS           | Not Necessary | 65.00 F    | *- FL        |
| 5   | 1   |          | *FRONT BONNET RUBBER                    | Cut           | 48.10 F    | *48.10 FL    |
| 6   | 1   |          | *FRONT BONNET LOCK                      | Damaged       | 84.50 F    | *84.50 FL    |
| 7   | 1   |          | *FRONT GRILLE                           | Cracked       | 181.50 F   | *181.50 FL   |
| 8   | 1   |          | *FRONT GRILLE TOP COVER                 | Deformed      | 23.00 F    | *23.00 FL    |
| 9   | 1   |          | *FRONT GRILLE CHROME                    | Cracked       | 193.20 F   | *193.20 FL   |
| 10  | 1   |          | *FRONT GRILLE EMBLEM LOGO               | Necessary     | 27.40 F    | *27.40 FL    |
| 11  | 1   |          | *FRONT GRILLE CLIP<br>(6 PCS)           | Necessary     | 39.00 F    | *20.00 FL    |
| 12  | 1   |          | *FRONT GRILLE LOWER                     | Not Necessary | 96.20 F    | *- FL        |
| 13  | 1   |          | *FRONT NUMBER PLATE                     | Cracked       | 50.00 F    | *50.00 FL    |
| 14  | 1   |          | *FRONT NUMBER PLATE GARNISH             | Cracked       | 80.00 F    | *80.00 FL    |
| 15  | 2   |          | *FRONT HEADLAMP                         | Cracked       | 1,279.60 F | *1,279.60 FL |
| 16  | 2   |          | *FRONT HEADLAMP LOWER BRACKET           | Bent          | 58.00 F    | *58.00 FL    |
| 17  | 1   |          | *FRONT BUMPER                           | Deformed      | 579.50 F   | *579.50 FL   |
| 18  | 10  |          | *FRONT BUMPER CLIP                      | Necessary     | 65.00 F    | *30.00 FL    |
| 19  | 1   |          | *FRONT BUMPER LOWER GRILLE              | Deformed      | 96.20 F    | *96.20 FL    |
| 20  | 2   |          | *FRONT BUMPER FOG LAMP COVER            | Not Necessary | 76.40 F    | *- FL        |
| 21  | 1   |          | *FRONT BUMPER REINFORCEMENT             | Distorted     | 377.90 F   | *377.90 FL   |
| 22  | 1   |          | *FRONT FENDER                           | N/S Buckled   | 1,136.00 F | *568.00 FL   |
| 23  | 1   |          | *FRONT SUPPORT PANEL                    | Buckled       | 574.50 F   | *574.50 FL   |
| 24  | 1   |          | *FRONT AIR CON CONDENSER                | Distorted     | 704.40 F   | *704.40 FL   |
| 25  | 1   |          | *FRONT AIR CON CONDENSER FAN MOTOR ASSY | Cracked       | 464.00 F   | *464.00 FL   |
| 26  | 1   |          | *FRONT AIR CON CONDENSER SECTION PIPE   | Bent          | 130.00 F   | *130.00 FL   |
| 27  | 1   |          | *FRONT AIR CON CONDENSER DISCHARGE PIPE | Bent          | 180.00 F   | *180.00 FL   |
| 28  | 1   |          | *FRONT RADIATOR                         | Bent          | 1,100.50 F | *1,100.50 FL |
| 29  | 1   |          | *FRONT RADIATOR FAN MOTOR ASSY          | Cracked       | 438.10 F   | *438.10 FL   |
| 30  | 2   |          | *FRONT BUMPER SIDE RETAINER             | Necessary     | 50.00 F    | *50.00 FL    |

F=Franchise part. L=ListItemDisc.

**Sub Total (\$\$)**    **9,030.90**    **7,983.70**  
**- List Item Discount on L Items 0.00/20.00% (\$\$)**    0.00    1,596.74

**Total Parts (\$\$)**    **9,030.90**    **6,386.96**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                                              | Lab.Type | Repairer's      | Amount          |
|--------------------------------|--------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>     |                                                                          |          |                 |                 |
| 1                              | TO REMOVE & REFIT AIR-CON<br>CONDENSER ,RADIATOR ,FAN MOTOR & TOP UP GAS | New      | 120.00          | 120.00          |
| 2                              | TO CHECK WIRING                                                          | New      | 100.00          | 30.00           |
| 3                              | TOWING FEE                                                               | New      | 150.00          | 60.00           |
| 4                              | TUFF KOTE                                                                | New      | 150.00          | 40.00           |
| 5                              | TOWING                                                                   | New      | 150.00          | 0.00            |
| 6                              | PANEL BEATING                                                            | New      | 1,200.00        | 900.00          |
| 7                              | SPRAY PAINTING                                                           | New      | 1,200.00        | 1,000.00        |
| <b>Gross Labour Cost (S\$)</b> |                                                                          |          | <b>3,070.00</b> | <b>2,150.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >