

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21000477/APA3Q2
Date: 06/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070130550
Claimant Vehicle No :	SLH3075E	Insured Vehicle No :	GBJ9097K
Date of Loss:	19/11/2020	Nature of Claim:	TP
		Claim No:	8655395979SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH3075E		
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Engine No:	L15B4402266
Reg. Date:	28/10/2016 (Man. Year: 2016)	Chassis No:	RU11202266
Colour:	Silver	Odometer:	271286 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,584.20	2,866.56	4,717.64	62.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,190.00	1,550.00	640.00	29.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,774.20	4,416.56	5,357.64	54.81
Approved Total (Overridden) (S\$)		3,500.00		

Nett Amount (S\$)	9,774.20	3,500.00	6,274.20	64.19
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
Nett Liability (S\$)		3,900.00		
Global Sum Settlement (S\$)		3,900.00		

INSPECTION

Date of Assignment: 05/01/2021

Date Inspected: 05/01/2021 Inspected At:

Sw Werkz Pte Ltd (HQ)
BLK 25 KAKI BUKIT ROAD 4, #03-67/68 SYNERGY @ KAKI BUKIT
Singapore 417800

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Distorted	821.10 F	*821.10 FL
2	2		*REAR BOOT LID HINGES	Not Necessary	224.00 F	*- FL
3	1		*REAR BOOT LID EMBLE LOGO	Not Necessary	55.00 F	*- FL
4	1		*REAR BOOT LID VEZEL LOGO	Necessary	38.10 F	*38.10 FL
5	1		*REAR BOOT LID SIDE REFLECTOR	N/S Cut	650.20 F	*325.10 FL
6	1		*REAR BOOT LID INNER RUBBER	Cut	185.20 F	*185.20 FL
7	1		*REAR BOOT LID INNER LOCK	Damaged	284.20 F	*284.20 FL
8	1		*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*- FL
9	2		*REAR BOOT LID NUMBER PLATE LAMP	Not Necessary	122.20 F	*- FL
10	1		*REAR BOOT LID CENTER MOULDING	Not Necessary	255.30 F	*- FL
11	10		*REAR BOOT LID INNER TRIM BOARD CLIPS	Necessary	50.00 F	*30.00 FL
12	1		*REAR BOOT LID INNER TRIM BOARD	Cracked	382.20 F	*382.20 FL
13	2		*REAR TAIL LAMP	Not Necessary	776.40 F	*- FL
14	1		*REAR END PANEL	Repair	420.00 F	*- FL
15	1		*REAR END PANEL TOP GARNISH	Deformed	188.00 F	*188.00 FL
16	1		*REAR BUMPER	Deformed	745.30 F	*745.30 FL
17	2		*REAR BUMPER SIDE BRACKET	Necessary	136.00 F	*136.00 FL
18	1		*REAR BUMPER REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
19	2		*REAR BUMPER REVERSE CAMERA (NPA)	Not Necessary	0.00 F	*- FL
20	2		*REAR SIDE BUMPER	Repair	450.00 F	*- FL
21	8		*REAR BUMPER CLIPS	Necessary	40.00 F	*40.00 FL
22	1		*REAR EXHAUST ALUMINIUM COVER	Not Necessary	95.00 F	*- FL
23	1		*REAR WINDSCREEN MOULDING	Necessary	158.00 F	*158.00 FL
24	1		*REAR SPARE TIRE PANEL LOWER COVER	Not Necessary	428.00 F	*- FL
25	2		*REAR SPARE TIRE PANEL LOWER PUMP	Not Necessary	580.00 F	*- FL
26	1		*REAR SPARE TIRE PANEL SEALANT	Not Necessary	200.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,584.20	3,533.20
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	666.64
Total Parts (\$\$)	7,584.20	2,866.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIX CUSHION	New	120.00	60.00
2	TO REMOVE & REFIX REAR WINDSCREEN	New	120.00	120.00
3	GUM	New	50.00	50.00
4	TO REMOVE & REFIX REVERSE SENSOR	New	120.00	50.00
5	TUFF KOTE	New	120.00	40.00
6	TO CHECK WIRING SYSTEM	New	60.00	30.00
7	PANEL BEATING	New	800.00	600.00
8	SPRAY PAINTING	New	800.00	600.00
Gross Labour Cost (S\$)			2,190.00	1,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >