

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21000479/APA3Q2
Date: 14/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070153082
Claimant Vehicle No :	SMS1539C	Insured Vehicle No :	SMW554T
Date of Loss:	05/01/2021	Nature of Claim:	TP
		Claim No:	8957485477SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS1539C	Engine No:	B14NET19SN8694
Make & Model:	OPEL ZAFIRA TOURER, 1.4 Turbo (A)	Chassis No:	W0VPE9EC9J1095618
Reg. Date:	13/02/2020 (Man. Year: 2018)	Odometer:	18536 km
Colour:	Black		
Engine Capacity:	1364 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,006.40	8,308.50	6,697.90	44.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,475.00	4,305.00	4,170.00	49.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	23,481.40	12,613.50	10,867.90	46.28
+ GST 7.00/7.00% (S\$)	1,643.70	882.95	760.75	46.28

Nett Amount (S\$)	25,125.10	13,496.45	11,628.65	46.28
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		13,738.45		

INSPECTION

Date of Assignment: 06/01/2021

Date Inspected: 06/01/2021

Estimated Period of Repair: 4.0 days

Inspected At: 1st Autoworks Pte Ltd (HQ)
23 Kaki Bukit Ave 4, #04-01
Singapore 415933

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	2,781.00 FL	*2,781.00 FL
2	1		*REAR TAILGATE WINDSCREEN WITH MOULDING	Not Necessary	1,480.00 FL	*- FL
3	1		*REAR TAILGATE CHROME MOULDING W LOGO	Not Necessary	216.00 FL	*- FL
4	1		*REAR TAILGATE OPENING SWITCH	Not Necessary	151.00 FL	*- FL
5	1		*REAR TAILGATE WIPE MOTOR	Not Necessary	656.00 FL	*- FL
6	1		*LETTERING ZAFIRA	Necessary	136.00 FL	*136.00 FL
7	1		*LETTERING TURBO	Necessary	68.00 FL	*68.00 FL
8	1		*LHR TAILGATE LAMP	Not Necessary	471.00 FL	*- FL
9	1		*RHR TAILGATE LAMP	Not Necessary	471.00 FL	*- FL
10	1		*TAILGATE LATCH	Damaged	308.00 FL	*308.00 FL
11	1		*TAILGATE STRIKER	Not Necessary	60.00 FL	*- FL
12	1		*TAILGATE INNER WEATHERSTRIP	Cut	434.00 FL	*434.00 FL
13	1		*TAILGATE INNER TRIM BOARD	Cracked	795.00 FL	*795.00 FL
14	1		*LH TAILGATE INNER TRIM BOARD UPPER	Not Necessary	180.00 FL	*- FL
15	1		*RH TAILGATE INNER TRIM BOARD UPPER	Not Necessary	180.00 FL	*- FL
16	1		*LH TAILGATE HINGE	Not Necessary	54.00 FL	*- FL
17	1		*RH TAILGATE HINGE	Not Necessary	54.00 FL	*- FL
18	1		*LH TAILGATE DAMPER	Not Necessary	220.00 FL	*- FL
19	1		*RH TAILGATE DAMPER	Not Necessary	220.00 FL	*- FL
20	1		*LHR TAILLAMP	Cut	590.00 FL	*590.00 FL
21	1		*RHR TAILLAMP	Not Necessary	590.00 FL	*- FL
22	1		*REAR BUMPER	Deformed	1,431.00 FL	*1,431.00 FL
23	1		*REAR BUMPER TOWING COVER	Not Necessary	87.00 FL	*- FL
24	1		*LHR BUMPER REFLECTOR	Missing	240.00 FL	*240.00 FL
25	1		*RHR BUMPER REFLECTOR	Not Necessary	240.00 FL	*- FL
26	1		*REAR BUMPER LOWER MOULDING	Deformed	290.00 FL	*290.00 FL
27	1		*REAR END PANEL TRIM	Deformed	199.00 FL	*199.00 FL
28	1		*REAR BUMPER SPONGE	Cracked	135.00 FL	*135.00 FL
29	1		*REAR BUMPER REINFORCEMENT BAR	Bent	529.00 FL	*529.00 FL
30	1		*REAR BUMPER GUIDE LOWER PANEL CENTRE	Necessary	65.00 FL	*65.00 FL
31	1		*REAR BUMPER GUIDE LOWER LH INNER	Necessary	68.00 FL	*68.00 FL
32	1		*REAR BUMPER GUIDE LOWER RH INNER	Necessary	68.00 FL	*68.00 FL
33	1		*REAR BUMPER GUIDE RH OUTER	Cracked	64.00 FL	*64.00 FL
34	1		*REAR BUMPER GUIDE LH OUTER	Cracked	64.00 FL	*64.00 FL
35	1		*REAR END PANEL INNER	Repair	585.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR END PANEL OUTER LOWER	Repair	443.00 FL	*- FL
37	10		*REAR BUMPER CLIP	Necessary	65.00 FL	*30.00 FL
38	8		*REAR FENDER LINER CLIPS	Not Necessary	52.00 FL	*- FL
39	8		*REAR END PANEL TRIM CLIP	Necessary	52.00 FL	*20.00 FL
40	1		*SET REVERSE SENSOR	Damaged	440.00 FL	*440.00 FL
41	1		*REAR REVERSE CAMERA	Not Necessary	280.00 FL	*- FL
42	1		*REAR END PANEL INSULATION SEAL	Not Necessary	120.00 FL	*- FL
43	16		*REAR FENDER INNER TRIM CLIP	Not Necessary	104.00 FL	*- FL
44	10		*TAIL GATE INNER TRIM BOARD CLIP	Necessary	65.00 FL	*30.00 FL
45	10		*TAIL GATE INNER UPPER TRIM BOARD CLIP	Not Necessary	65.00 FL	*- FL
46	1		*REAR NUMBER PLATE	Not Necessary	45.00 FS	*- FS
47	1		*TAILGATE WINDSCREEN SEALANT	Necessary	120.00 FS	*60.00 FS
48	1		*TAILGATE WINDSCREEN SOLAR FILM	Not Necessary	220.00 FS	*- FS
49	1		*REVERSE SENSOR WIRE HARNESS	Cracked	320.00 FL	*320.00 FL
50	1		*RR BUMPER LOW BRACKET	Necessary	60.00 FL	*60.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	16,631.00	9,225.00
- List Item Discount on L Items 10.00/10.00% (\$)	1,624.60	916.50
Total Parts (\$)	15,006.40	8,308.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	3,900.00	1,950.00
2	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA	New	3,300.00	1,650.00
3	TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT	New	130.00	80.00
4	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	130.00	30.00
5	TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST	New	130.00	60.00
6	TO REMOVE AND REFIX REVERSE CAMERA AND CONDUCT TEST	New	130.00	60.00
7	TO CONDUCT TRANSFER OF PARTS FROM OLD TAILGATE TO NEW TAILGATE	New	195.00	80.00
8	TO CONDUCT WATER LEAKAGE TEST AFTER REPAIRS OF VEHICLE	New	65.00	0.00
9	TO REFIX NEW REAR TAIL GATE WINDSCREEN	New	195.00	195.00
10	S.R.S RESET OF SYSTEM	New	300.00	200.00
Gross Labour Cost (\$\$)			8,475.00	4,305.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >