

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG21000491/T1TF3E2

**Date:** 29/01/2021

### REFERENCE

|                              |                                      |                             |            |           |              |
|------------------------------|--------------------------------------|-----------------------------|------------|-----------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 2100238096 |           |              |
| <b>Claimant Vehicle No :</b> | SMS6992T                             | <b>Insured Vehicle No :</b> | SJA3531R   |           |              |
| Date of Loss:                | 10/01/2021                           | Nature of Claim:            | TP         | Claim No: | 0367656983SG |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |             |
|-----------------------------|-----------------------------------|-------------|-------------|
| Reg No:                     | <b>SMS6992T</b>                   | Engine No:  | L13B3930358 |
| Make & Model:               | HONDA FIT, 1.3 GF CVT (A)         | Chassis No: | GK33415867  |
| Reg. Date:                  | 10/03/2020 (Man. Year: 2019)      | Odometer:   | 11826 km    |
| Colour:                     | Blue                              |             |             |
| Engine Capacity:            | 1317 cc                           |             |             |
| Market Value/New Car Price: | N/A                               |             |             |
| Sum Insured (\$\$):         | <b>Market Value/New Car Price</b> |             |             |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 175/70 R14    | Rear Tyre Size:  | 175/70 R14    |
| Front Left Side:  | Yokohama 6 mm | Rear Left Side:  | Yokohama 6 mm |
| Front Right Side: | Yokohama 6 mm | Rear Right Side: | Yokohama 6 mm |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS            | Repairer's  | Adjuster's  | Difference  | Diff % |
|---------------------------|-------------|-------------|-------------|--------|
| Parts                     | 0.00        | 0.00        | 0.00        |        |
| Miscellaneous Items       | 0.00        | 0.00        | 0.00        |        |
| Labour                    | 0.00        | 0.00        | 0.00        |        |
| Paintwork Labour          | 0.00        | 0.00        | 0.00        |        |
| Towing                    | 0.00        | 0.00        | 0.00        |        |
| <b>Nett Amount (\$\$)</b> | <b>0.00</b> | <b>0.00</b> | <b>0.00</b> |        |

### INSPECTION

|                             |            |  |
|-----------------------------|------------|--|
| Date of Assignment:         | 11/01/2021 |  |
| Date Inspected:             | 12/01/2021 | Inspected At: Garage 13 Pte Ltd (HQ)<br>8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #03-46<br>Singapore 415875 |
| Estimated Period of Repair: | 6.0 days   |  |

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

| No. | Qty | Part No. | Particulars                   | Condition | Repairer's                | Amount           |
|-----|-----|----------|-------------------------------|-----------|---------------------------|------------------|
| 1   | 1   |          | *FRT BUMPER                   | Deformed  | 0.00 F                    | *- F             |
| 2   | 1   |          | *FRT BUMPER CLIPS             | Necessary | 0.00 F                    | *- F             |
| 3   | 1   |          | *FRT BUMPER SIDE RETAINER     | Deformed  | 0.00 F                    | *- F             |
| 4   | 1   |          | *FRT LH BUMPER FOG LAMP COVER | Cut       | 0.00 F                    | *- F             |
| 5   | 1   |          | *FRT LH HEADLAMP ASSY         | Cracked   | 0.00 F                    | *- F             |
| 6   | 1   |          | *FRT LH FENDER                | Bent      | 0.00 F                    | *- F             |
| 7   | 1   |          | *FRT LH FENDER INNER PANEL    | Repair    | 0.00 F                    | *- F             |
| 8   | 1   |          | *FRT LH FENDER INNER SHIELD   | Deformed  | 0.00 F                    | *- F             |
| 9   | 1   |          | *FRT LH WHEEL RIM             | Cut       | 0.00 F                    | *- F             |
| 10  | 1   |          | *FRT LH WING MIRROR           | Repair    | 0.00 F                    | *- F             |
| 11  | 1   |          | *FRT LH DOOR                  | Repair    | 0.00 F                    | *- F             |
| 12  | 1   |          | *FRT LH SHOCK ABSORBER        | * Check   | 0.00 F                    | *- F             |
| 13  | 1   |          | *FRT LH KNUCKLE ARM           | * Check   | 0.00 F                    | *- F             |
| 14  | 1   |          | *FRT LH KNUCKLE ARM BEARING   | * Check   | 0.00 F                    | *- F             |
| 15  | 1   |          | *FRONT LH LOWER ARM           | * Check   | 0.00 F                    | *- F             |
|     |     |          |                               |           | F=Franchise part.         |                  |
|     |     |          |                               |           | <b>Total Parts (\$\$)</b> | <b>0.00 0.00</b> |

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

There are no labour items selected.

|   |
|---|
| Report was unsubmitted during this print-out. |
|---|

< END OF ESTIMATES >