

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21000493/GVD3E2

Date: 27/01/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070036696		
Claimant Vehicle No :	SLQ4559Y	Insured Vehicle No :	YP7024E		
Date of Loss:	09/01/2021	Nature of Claim:	TP	Claim No:	8491864578SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ4559Y	Engine No:	L15B4408165
Make & Model:	HONDA VEZEL, 1.5 X (A)	Chassis No:	RU11208169
Reg. Date:	11/07/2017 (Man. Year: 2016)	Odometer:	75660 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	11/01/2021		
Date Inspected:	12/01/2021	Inspected At:	Garage 13 Pte. Ltd. (HQ) 8 Kaki Bukit Avenue 4, #03-46 Premier Singapore 415875
Estimated Period of Repair:	4.0 days		

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Broken	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*FRT BUMPER BRACKET	Broken	0.00 F	*- F
4	1		*FRT BUMPER SIDE RETAINER	Broken	0.00 F	*- F
5	1		*FRT GRILLE	Cracked	0.00 F	*- F
6	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
7	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
8	1		*BONNET	Repair	0.00 F	*- F
9	1		*BONNET RUBBER	Cut	0.00 F	*- F
10	1		*FRT RH FENDER	Buckled	0.00 F	*- F
11	1		*FRT RH FENDER PROTECTOR	Scratched	0.00 F	*- F
12	1		*FRT RH FENDER INNER SHIELD	Crumpled	0.00 F	*- F
13	1		*FRT RH DOOR	Repair	0.00 F	*- F
F=Franchise part.						
					Total Parts (\$\$)	0.00 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >