

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21000495/ETF3E2

Date: 02/03/2021

REFERENCE

| | | | | | |
|-------------------|-------------|------------------|------------|-----------|--------------|
| Insured/Claimant: | SZE TAKLOON | Policy No: | 1800154172 | | |
| Date of Loss: | 08/01/2021 | Nature of Claim: | OD | Claim No: | 0372451868SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No: | SMG8934L | | |
| Make & Model: | KIA CERATO, 1.6 (A) | Engine No: | G4FGJH709098 |
| Reg. Date: | 03/01/2019 (Man. Year: 2018) | Chassis No: | KNAF3416MK5018263 |
| Colour: | Silver | Odometer: | 47449 km |
| Engine Capacity: | 1591 cc | | |
| Market Value/New Car Price: | S\$73,000.00 | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|------------|------------------|------------|
| Front Tyre Size: | 205/55 R16 | Rear Tyre Size: | 205/55 R16 |
| Front Left Side: | Kumho 5 mm | Rear Left Side: | Kumho 5 mm |
| Front Right Side: | Kumho 5 mm | Rear Right Side: | Kumho 5 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|-----------------|-----------------|---------------|--------------|
| Parts | 1,278.80 | 1,081.60 | 197.20 | 15.42 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,420.00 | 1,020.00 | 400.00 | 28.17 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 2,698.80 | 2,101.60 | 597.20 | 22.13 |
| + GST 7.00/7.00% (S\$) | 188.92 | 147.11 | 41.81 | 22.13 |
| Nett Amount (S\$) | 2,887.72 | 2,248.71 | 639.01 | 22.13 |

INSPECTION

| | | | |
|-----------------------------|------------|---------------|---|
| Date of Assignment: | 12/01/2021 | | |
| Date Inspected: | 13/01/2021 | Inspected At: | Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339 |
| Estimated Period of Repair: | 3.0 days | | |

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|---|-----|----------|---------------------------------|---------------|-------------|--------------|
| 1 | 1 | | *SUNDRIES | Necessary | 50.00 FS | *20.00 FS |
| 2 | 1 | | *PANEL ASSY-FRONT DOOR, RH | Dented | 1,277.00 FL | *1,277.00 FL |
| 3 | 1 | | *W/STRIP ASSY-FR DR BELT O/S RH | Not Necessary | 64.00 FL | *- FL |
| 4 | 1 | | *W/STRIP ASSY-FR DR SIDE RH | Not Necessary | 102.00 FL | *- FL |
| 5 | 1 | | *W/STRIP-FR DR BELT I/S RH | Not Necessary | 43.00 FL | *- FL |
| 6 | 1 | | *BLACK TAPE-FR DR RR, RH | Necessary | 13.00 FL | *13.00 FL |
| 7 | 1 | | *MOULDING ASSY-FRT DR FRAME, RH | Necessary | 37.00 FL | *37.00 FL |
| F=Franchise part. S=SpcNett. L=ListItemDisc. | | | | | | |
| Sub Total (\$\$) | | | | | 1,586.00 | 1,347.00 |
| - List Item Discount on L Items 20.00/20.00% (\$\$) | | | | | 307.20 | 265.40 |
| Total Parts (\$\$) | | | | | 1,278.80 | 1,081.60 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | REPLACE FRT RH DOOR PANEL & AFFECTED AREA | New | 800.00 | 400.00 |
| 2 | PAINT WORK ON FRT RH DOOR PANEL | New | 350.00 | 350.00 |
| 3 | TRANSFER FRT RH DOOR ATTACHMENT TO NEW PANEL | New | 120.00 | 120.00 |
| 4 | CHECK WIRING & CHASSIS ELECTRICAL SYSTEM | New | 30.00 | 30.00 |
| 5 | TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST | New | 120.00 | 120.00 |
| Gross Labour Cost (\$\$) | | | 1,420.00 | 1,020.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >