

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III21000504/UQD3Q2

Date: 25/01/2021

REFERENCE

| | | | |
|------------------------------|---------------------------------------|-----------------------------|------------------|
| Handling Insurer: | India International Insurance Pte Ltd | Policy No: | D19MCV0005219_01 |
| Claimant Vehicle No : | SGW8797C | Insured Vehicle No : | GBE2067U |
| Date of Loss: | 05/01/2021 | Nature of Claim: | TP |
| | | Claim No: | MCV2021D0000249 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SGW8797C | | |
| Make & Model: | SUZUKI VITARA, 1.6 (A) | Engine No: | M16A2270177 |
| Reg. Date: | 11/02/2019 (Man. Year: 2018) | Chassis No: | TSMLYD21S00507060 |
| Colour: | Beige | Odometer: | 46082 km |
| Engine Capacity: | 1586 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (\$\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size: | 215/55 R17 | Rear Tyre Size: | 215/55 R17 |
| Front Left Side: | Continental 6 mm | Rear Left Side: | Continental 6 mm |
| Front Right Side: | Continental 6 mm | Rear Right Side: | Continental 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-------------------|-------------------|-------------------|---------------|
| Parts | 7,811.70 | 4,684.58 | 3,127.12 | 40.03 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 3,640.00 | 1,870.00 | 1,770.00 | 48.63 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (\$\$) | 11,451.70 | 6,554.58 | 4,897.12 | 42.76 |
| Approved Total (Overridden) (\$\$) | | 5,200.00 | | |
| (\$\$) | 11,451.70 | 5,200.00 | 6,251.70 | 54.59 |
| + GST 7.00/7.00% (\$\$) | 801.62 | 364.00 | 437.62 | 54.59 |
| Nett Amount (\$\$) | 12,253.32 | 5,564.00 | 6,689.32 | 54.59 |

INSPECTION

| | | | |
|-----------------------------|------------|---------------|---------------------|
| Date of Assignment: | 11/01/2021 | Inspected At: | Tick Hai Motor (HQ) |
| Date Inspected: | 12/01/2021 | | AUTOBAY#01-54 |
| | | | Singapore 435435 |
| Estimated Period of Repair: | 4.0 days | | |

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|---|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 22 Jan 2021) |
| Parts: | M1-SUV | SUZUKI VITARA 1.6 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SGW8797C) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--------------------------------------|--------------------|-------------|--------------|
| 1 | 1 | | *REAR TAILGATE | Dented / Bent | 1,043.25 FL | *1,043.25 FL |
| 2 | 1 | | *REAR BOOT LAMP | O/S Cracked | 529.65 FL | *264.82 FL |
| 3 | 1 | | *REAR BOOT LOCK | Serviceable | 160.50 FL | *- FL |
| 4 | 1 | | *REAR BOOT CATCH | Not Necessary | 24.08 FL | *- FL |
| 5 | 1 | | *REAR BOOT RUBBER | Twisted | 160.50 FL | *160.50 FL |
| 6 | 1 | | *SUZUKI EMBLEM | Necessary | 31.00 FL | *31.00 FL |
| 7 | 1 | | *VITARA EMBLEM | Necessary | 48.00 FL | *48.00 FL |
| 8 | 1 | | *REAR BOOT INNER TRIMBOARD | Deformed / Cracked | 345.08 FL | *345.08 FL |
| 9 | 1 | | *REAR NUMBER PLATE TOP GARNISH | Cracked | 337.05 FL | *337.05 FL |
| 10 | 2 | | *NUMBER PLATE LAMP | Not Necessary | 81.20 FL | *- FL |
| 11 | 1 | | *TAILLAMP | O/S Cracked | 770.40 FL | *385.20 FL |
| 12 | 1 | | *REAR WIPER MOTOR | Not Necessary | 302.50 FL | *- FL |
| 13 | 1 | | *REAR BUMPER | Deformed | 1,011.15 FL | *1,011.15 FL |
| 14 | 2 | | *REAR BUMPER REFLECTOR | Not Necessary | 38.52 FL | *- FL |
| 15 | 2 | | *REAR BUMPER SIDE RETAINERS | Not Necessary | 38.52 FL | *- FL |
| 16 | 1 | | *REAR BUMPER DIFFUSER | Deformed | 304.95 FL | *304.95 FL |
| 17 | 1 | | *REAR BUMPER DIFFUSER COVER (SILVER) | Deformed | 60.99 FL | *60.99 FL |
| 18 | 1 | | *REAR BUMPER REINFORCEMENT | Bent | 240.75 FL | *240.75 FL |
| 19 | 2 | | *REAR BUMPER AIR VENT | Not Necessary | 67.41 FL | *- FL |
| 20 | 1 | | *END PANEL | Dented | 568.20 FL | *568.20 FL |
| 21 | 1 | | *END PANEL TOP GARNISH | Twisted | 160.50 FL | *160.50 FL |
| 22 | 1 | | *CRASH SENSOR | Not Necessary | 240.75 FL | *- FL |
| 23 | 1 | | *REAR WINDSCREEN MOULDING (2 PCS) | Necessary | 80.25 FL | *80.25 FL |
| 24 | 1 | | *SET CLIP REAR BUMPER | Necessary | 128.40 FL | *128.40 FL |
| 25 | 1 | | *REAR EXHAUST | Repair | 1,011.61 FL | *- FL |
| 26 | 1 | | *REAR BUMPER DIFFUSER COVER (BLACK) | Not Necessary | 72.23 FL | *- FL |
| 27 | 1 | | *WINDSCREEN SEALANT | Necessary | 80.00 FS | *40.00 FS |
| 28 | 1 | | *END PANEL SEALANT | Necessary | 50.00 FS | *50.00 FS |
| 29 | 1 | | *REAR NUMBER PLATE WITH CASING | Not Necessary | 60.00 FS | *- FS |
| 30 | 4 | | *REVERSE SENSOR | Shorted | 400.00 FS | *200.00 FS |
| 31 | 1 | | *REVERSE CAMERA | Not Necessary | 150.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$) | 8,597.44 | 5,460.09 |
| - List Item Discount on L Items 10.00/15.00% (\$) | 785.74 | 775.51 |
| Total Parts (\$) | 7,811.70 | 4,684.58 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|---|----------|-----------------|-----------------|
| <u>Labour Items</u> | | | | |
| 1 | TO REMOVE ,AND REINSTALL REVERSE SENSORS | New | 80.00 | 50.00 |
| 2 | TO CHECK REAR ELECTRICAL WIRING SYSTEM | New | 50.00 | 20.00 |
| 3 | TO TRANSFER REAR WINDSCREEN TO NEW TAILGATE | New | 150.00 | 120.00 |
| 4 | TO TRANSFER TAILGATE COMPONENT TO NEW TAILGATE | New | 150.00 | 60.00 |
| 5 | TO APPLY ANTI-RUSTING COATING ON NEW PANELS | New | 200.00 | 60.00 |
| 6 | TO REMOVE & REINSTALL REAR INTERIOR TRIM FOR NECESSARY REPAIR | New | 180.00 | 80.00 |
| 7 | TO REMOVE & REINSTALL EXHAUST | New | 150.00 | 0.00 |
| 8 | TO REMOVE & REINSTALL SPARE TYRE | New | 80.00 | 0.00 |
| 9 | LABOUR TO REMOVE ,CUT ,CHARGE & PANEL BEATING | New | 1,400.00 | 600.00 |
| 10 | TO PUTTY AND RESPRAY AFFECTED AREAS | New | 1,200.00 | 880.00 |
| Gross Labour Cost (S\$) | | | 3,640.00 | 1,870.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >