

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21000506/KQF3Q2

Date: 19/02/2021

REFERENCE

Insured/Claimant: DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.

Policy No: 0999993880

Date of Loss: 17/12/2020

Nature of Claim:

OD

Claim No:

6168884530SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBH5296P**

Make & Model: MERCEDES-BENZ VITO 109, 1.6 CDI LONG (M)

Engine No: 65195034276730

Reg. Date: 29/06/2018 (Man. Year: 2017)

Chassis No: WDF44760323352154

Colour: Red

Odometer: 93437 km

Engine Capacity: 2143 cc

Market Value/New Car Price: S\$83,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16

Rear Tyre Size:

215/60R16

Front Left Side: Achilles 4 mm

Rear Left Side:

Achilles 6 mm

Front Right Side: Achilles 4 mm

Rear Right Side:

Achilles 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,713.80	1,556.80	157.00	9.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,830.00	480.00	1,350.00	73.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,543.80	2,036.80	1,507.00	42.52
- Excess (S\$)	1,400.00	1,400.00	0.00	0.00
(S\$)	2,143.80	636.80	1,507.00	70.30
+ GST 7.00/7.00% (S\$)	150.07	44.58	105.49	70.29
Nett Amount (S\$)	2,293.87	681.38	1,612.49	70.30

INSPECTION

Date of Assignment: 12/01/2021

Date Inspected: 12/01/2021 Inspected At:

Tong Luck Auto Pte Ltd (HQ)
160 Sin Ming Drive, #07-01 Sin Ming
AutoCity
Singapore 575722

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SLIDING DOOR-LH (WCP)	Bent	1,280.00 F	*1,280.00 F
2	1		*SLIDING DOOR OUTER HANDLE (LONG)-LH (WCP)	Dented	80.00 F	*80.00 F
3	1		*SLIDING DOOR OUTER HANDLE (SHORT)-LH (WCP)	Dented	28.00 F	*28.00 F
4	1		*SLIDING DOOR INNER TRIMBOARD-LH (WCP)	Serviceable	115.00 F	*- F
5	10		*SLIDING DOOR INNER TRIMBOARD CLIPS -LH (WCP)	Necessary	60.50 FS	*30.00 FS

F=Franchise part. S=SpcNett.

Sub Total (S\$)	1,563.50	1,418.00
+ Margin on L,N Items 10.00/10.00% (S\$)	150.30	138.80

Total Parts (S\$)	1,713.80	1,556.80
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	*OD/TP Case (Insurer)	-	0.00
Sub Total (\$\$)			0.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER LH DAMAGED SLIDING DOOR INTETTERIOR MECHANISM TO NEW DOOR	New	150.00	60.00
2	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	20.00
3	TO PANEL BEAT AND STRAIGHTEN LH REAR FENDER,LH RUNNING BOARD PANEL,INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY,TO REFIT AND ADJUST THE SAME	New	800.00	200.00
4	TO PUTTY AND SPRAY PAINT ON AFFECTED	New	800.00	200.00
Gross Labour Cost (\$\$)			1,830.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >