

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21000508/KVF3E2

Date: 23/02/2021

REFERENCE

Insured/Claimant: DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD. Policy No: 0999993862

Date of Loss: 28/12/2020

Nature of Claim: OD

Claim No: 8345268908SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMT1860T	Engine No:	CZP230061
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Chassis No:	WAUZZZF31L1050517
Reg. Date:	30/03/2020 (Man. Year: 2019)	Odometer:	16725 km
Colour:	Metallic Grey		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$180,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55R18	Rear Tyre Size:	235/55R18
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 9 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 9 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,991.60	7,323.50	3,668.10	33.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,080.00	1,120.00	1,960.00	63.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,071.60	8,443.50	5,628.10	40.00
- Excess (S\$)	1,200.00	1,200.00	0.00	0.00
(S\$)	12,871.60	7,243.50	5,628.10	43.72
+ GST 7.00/7.00% (S\$)	901.01	507.05	393.96	43.72
Nett Amount (S\$)	13,772.61	7,750.55	6,022.06	43.72

INSPECTION

Date of Assignment: 12/01/2021

Date Inspected: 12/01/2021 Inspected At:

Tong Luck Auto Pte Ltd (HQ)
160 Sin Ming Drive, #07-01 Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET (WCP)	Bent	1,600.00 F	*1,600.00 F
2	2		*BONNET HINGES-RH/LH (WCP)	Repair	116.00 F	*- F
3	10		*BONNET INSULATOR CLIPS (WCP)	Necessary	55.00 FS	*30.00 FS
4	1		*SUPPORT PANEL (WCP)	Serviceable	720.00 F	*- F
5	1		*SUPPORT PANEL TOP GARNISH (WCP)	Mtg Cracked	98.00 F	*98.00 F
6	10		*SUPPORT PANEL TOP GARNISH CLIPS (WCP)	Necessary	55.00 FS	*30.00 FS
7	1		*FRONT GRILLE ASSY (WCP)	Dented	980.00 F	*980.00 F
8	1		*FRONT GRILLE EMBLEM (WCP)	Necessary	85.00 F	*85.00 F
9	1		*HEADLAMP ASSY-LH (WCP)	Cracked	2,550.00 F	*2,550.00 F
10	2		*FRONT BUMPER-RH/LH (WCP)	Serviceable	1,560.00 F	*- F
11	1		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	520.00 F	*520.00 F
12	1		*FRONT BUMPER REINFORCEMENT COVER (WCP)	Cracked	235.00 F	*235.00 F
13	1		*FRONT BUMPER SPONGE (WCP)	Serviceable	85.00 F	*- F
14	1		*FRONT BUMPER LOWER GRILLE (WCP)	Serviceable	155.00 F	*- F
15	2		*FRONT BUMPER SENSORS (WCP)	Serviceable	336.00 F	*- F
16	4		*FRONT BUMPER SENSOR SEALS (WCP)	Not Necessary	24.00 F	*- F
17	2		*FRONT BUMPER FOG LAMP COVER-RH/LH (WCP)	Serviceable	250.00 F	*- F
18	1		*FRONT BUMPER CLIPS (WCP) (15 Pcs)	Necessary	82.50 FS	*50.00 FS
19	1		*FRONT NUMBER PLATE	Bent	40.00 FS	*25.00 FS
20	1		*BONNET SEAL (WCP) (Supplementary)	Necessary	28.00 F	*28.00 F
21	1		*FRONT GRILLE INNER PLATE (WCP) (Supplementary)	Cracked	236.00 F	*236.00 F
22	1		*FRONT GRILLE SUPPORT (WCP) (Supplementary)	Cracked	138.00 F	*138.00 F
23	1		*HEADLAMP MOUNTING-LH (WCP) (Supplementary)	Cracked	65.00 F	*65.00 F
					Sub Total (\$\$)	10,013.50 6,670.00
					+ Margin on L,N Items 10.00/10.00% (\$\$)	978.10 653.50
					Total Parts (\$\$)	10,991.60 7,323.50

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT AIR-CON CONDENSER,RADIATOR ASSY AND REFILL AIR-CON GAS	New	150.00	0.00
2	TO REMOVE AND REFIT FRONT BUMPER SENSOR	New	100.00	50.00
3	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	20.00
4	TO PANEL BEAT AND STRAIGHTEN LH FRONT FENDER.LH FRONT CHASSIS FRAME,INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY,TO REFIT AND ADJUST THE SAME	New	1,200.00	400.00
5	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS	New	1,200.00	400.00
6	TO RESET AND REPROGRAM HEADLAMP FAULT CODE	New	350.00	250.00
Gross Labour Cost (\$\$)			3,080.00	1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >