



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 28/12/2020

ESTIMATE

NO : QUOT202101-000015(00)

DATE : 12/01/2021

POLICY NO : 999995580

VEH REG NO : SMT1860T

MAKE/MODEL : AUDI Q3 SPORTBACK 2.0 TFSI
QU S TRONIC

CHASSIS NO : WAUZZZF31L1050517

ENGINE NO : CZP230061

REG. DATE : 2020

Estimate Repair Cost to Vehicle No : SMT1860T

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Bonnet	1	1,600.00	1,600.00 ✓
2 Bonnet hinges - RH / LH	2	58.00	116.00 X
3 Bonnet insulator clips	10	5.00	50.00 30sn
4 Support panel	1	720.00	720.00 X
5 Support panel top garnish	1	98.00	98.00 ✓
6 Support panel top garnish clips	10	5.00	50.00 30sn
7 Front grille assy	1	980.00	980.00 ✓
8 Front grille emblem	1	85.00	85.00 ✓
9 Headlamp assy - LH	1	2,550.00	2,550.00 ✓
10 Front bumper -- RH / LH	2	780.00	1,560.00 X
11 Front bumper reinforcement	1	520.00	520.00 X
12 Front bumper reinforcement cover	1	235.00	235.00 ✓
13 Front bumper sponge	1	85.00	85.00 X
14 Front bumper lower grille	1	155.00	155.00 X
15 Front bumper sensors	2	168.00	336.00 X
16 Front bumper sensor seals	4	6.00	24.00 X
17 Front bumper fog lamp cover - RH / LH	2	125.00	250.00 X
18 Front bumper clips	15	5.00	75.00 ✓
			9,489.00
			Add 10% 948.90
			10,437.90
SPECIAL NET			
19 Front number plate	1	40.00	40.00 25sn
			40.00
LABOUR			
20 To remove and refit air-con condenser, radiator assy and refill air-con gas	1	150.00	150.00 X
21 To remove and refit front bumper sensor	1	100.00	100.00 50d
22 To check and rectify wiring system	1	80.00	80.00 20d
23 To panel beat and straighten LH front fender, LH front chassis frame, including replacement of parts and align where necessary, to refit and adjust the same	1	1,200.00	1,200.00 400d
24 To putty and spray paint on affected areas	1	1,200.00	1,200.00 400d
25 To reset and reprogramme headlamp fault code	1	350.00	350.00 25d
			3,080.00

LKK Auto Consultants hence notify the Repairer of the following:
• To survey before/after spray painting
• To display damaged part(s) during survey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date: