



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBF 7250T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
2	FORK INNER TUBES (CONSISTENT)	BENT / TWISTED	280.00	280.00
2	FORK OUTER TUBES (CONSISTENT)	BENT / TWISTED	290.00	290.00
1	FORK UNDER BRACKET (CONSISTENT)	BENT	185.00	145.00
1	SET SIDE MIRROR (CONSISTENT)	BROKEN	96.00	96.00
2	SET FRONT SIGNALS (CONSISTENT)	CRACKED	70.00	70.00
1	HANDLE -BAR (CONSISTENT)	NOT NECESSARY	80.00	-
1	HANDLE -BAR BRACKET (CONSISTENT)	NOT NECESSARY	95.00	-
1	SET HAND GRIP (CONSISTENT)	NOT NECESSARY	25.00	-
1	BRAKE LEVER (CONSISTENT)	NOT NECESSARY	20.00	-
1	FRONT BRAKE DISC (CONSISTENT)	NOT NECESSARY	80.00	-
1	FRONT RIM (CONSISTENT)	BENT / WARPED	260.00	260.00
1	FRONT RIM SHAFT (CONSISTENT)	NOT NECESSARY	35.00	-
1	FRONT FOOTREST BRACKET (CONSISTENT)	NOT NECESSARY	55.00	-
1	FRONT FOOTREST RUBBERS (CONSISTENT)	NOT NECESSARY	56.00	-
1	BRAKE PEDAL (CONSISTENT)	NOT NECESSARY	42.00	-
1	REAR FOOTREST(CONSISTENT)	NOT NECESSARY	38.00	-
1	REAR FOOTREST BRACKET (CONSISTENT)	NOT NECESSARY	50.00	-
1	EXHAUST ASSY (DENTED)	NOT CONSISTENT WITH THE IMPACT	425.00	-
1	FRONT FENDER -MATT BLACK(CONSISTENT)	BROKEN	68.00	68.00
1	FRONT INNER COVER CENTRE (CONSISTENT)	CRACKED	45.00	45.00
1	SET FAIRING ASSY (CONSISTENT)	CRACKED	485.00	485.00
1	BASKET (CONSISTENT)	CRACKED	30.00	30.00
	LESS 10% DISCOUNT		-281.00	-176.90
			2,529.00	1,592.10
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET NUMBER PLATE (SN)(CONSISTENT)	BENT	28.00	10.00
2	FORK OILS (SN)(CONSISTENT)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN)(CONSISTENT)	NOT NECESSARY	56.00	-
1	SET STEERING CONE BEARING (SN)(CONSISTENT)	NECESSARY	85.00	50.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BOX (CUT) (SN)	NOT CONSISTENT WITH THE IMPACT	200.00	-
1	REAR BOX BRACKET (SN)(CONSISTENT)	NOT NECESSARY	100.00	-
1	SET STICKER (SN)(CONSISTENT)	NOT NECESSARY	60.00	-
1	E.R.P IU (SN)(CONSISTENT)	NOT NECESSARY	200.00	-
			759.00	60.00
	<b>LABOUR</b>			
	TO PROVIDE TOWING.		50.00	35.00
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO REPAIR BODY FRAME.		480.00	250.00
	TO PROVIDE LABOUR.		420.00	280.00
			1,030.00	565.00
<b>GRAND TOTAL</b>			<b>4,318.00</b>	<b>2,217.10</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,200.00</b>

Report Ref No. CC4/ASM21000512/Ups3q2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.