




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

| PRE-REPAIR INSPECTION REPORT | | | | |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------|---------------------|---------------------------------------------------------------------------------------|--|
| LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555 | | | Ref: CS3/LPC21000513/Gqd3e2 Date: 14/01/2021 Code: LPC2 | |
| 1. Policy Particulars :- (THIRD PARTY CLAIM) | | | | |
| Insured Veh. | SLA 4148J | Veh. Inspected | SJT 1365S | |
| Policy No. | | Coverage (\$) | 0.00 | |
| Claim No. | 20/21/21/VP05/024115 | Excess (\$) | 0.00 | |
| Assign From | ONG LI LI | Assign Date | 11/01/2021 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | TOYOTA VIOS | c.c | 1497 | |
| Engine No. | HIDDEN | Year of Reg. | 2009 | |
| Chassis No. | MR053HY9305131182 | Colour | BLUE | |
| Odometer | 230662 KM | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | SPORTS RIM | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 205/45 ZR16 | TOURADOR | 6 mm | |
| L/H Front Tyre | 205/45 ZR16 | TOURADOR | 6 mm | |
| R/H Rear Tyre | 205/45 ZR16 | TOURADOR | 6 mm | |
| L/H Rear Tyre | 205/45 ZR16 | TOURADOR | 6 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. | | |  | |
| 5. General Information | | | | |
| Accident Date | 09/01/2021 | Inspect Date / Time | 12/01/2021 (12:00 PM) | |
| Survey held at | GARAGE 13 PTE LTD 8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE. | | | |
| 5a. Remarks | | | | |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. | | | | |

Report Ref No. CS3/LPC21000513/Gqd3e2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.