

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21000517/APS3Q2
Date: 11/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100187436
Claimant Vehicle No :	SME9060L	Insured Vehicle No :	GBB7662J
Date of Loss:	08/01/2021	Nature of Claim:	TP
		Claim No:	6782362540SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME9060L		
Make & Model:	MERCEDES-BENZ CLA180, 1.6 AMG (A)	Engine No:	27091031551957
Reg. Date:	26/06/2018 (Man. Year: 2017)	Chassis No:	WDD1173422N626183
Colour:	White	Odometer:	76627 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/40R18	Rear Tyre Size:	225/40R18
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,500.30	6,875.60	1,624.70	19.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,750.00	640.00	1,110.00	63.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,250.30	7,515.60	2,734.70	26.68
Approved Total (Overridden) (S\$)		6,000.00		

Nett Amount (S\$)	10,250.30	6,000.00	4,250.30	41.47
+ Car Rental (6.0 x S\$110.00/day) (S\$)		660.00		
Nett Liability (S\$)		6,660.00		

INSPECTION

Date of Assignment: 11/01/2021

Date Inspected: 11/01/2021

Inspected At:

Advance Auto Garage (HQ)
 23 KAKI BUKIT AVENUE 4 #04-01 AAS KAKI BUKIT CENTRE
 Singapore 415933

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,392.00 FL	*1,392.00 FL
2	1		*FRONT BUMPER SIDE HOLDER RH	Necessary	106.00 FL	*106.00 FL
3	1		*FRONT BUMPER TOW COVER	Missing	45.00 FL	*45.00 FL
4	1		*FRONT BUMPER REINFORCEMENT	Bent	585.00 FL	*585.00 FL
5	1		*FRONT BUMPER SPONGE	Deformed	234.00 FL	*234.00 FL
6	1		*FRONT BUMPER LOWER GARNISH	Cut	385.00 FL	*385.00 FL
7	1		*FRONT BUMPER SIDE GRILLE RH	Cracked	255.00 FL	*255.00 FL
8	2		*FRONT BUMPER SENSOR	Damaged (1 PCS ONLY)	530.00 FL	*265.00 FL
9	1		*FRONT BUMPER INNER FRAME	Cracked	185.00 FL	*185.00 FL
10	1		*FRONT BUMPER UNDERCOVER	Cracked	329.00 FL	*329.00 FL
11	1		*FRONT BUMPER LOWER GRILLE	Cracked	282.00 FL	*282.00 FL
12	1		*FRONT BUMPER LOGO	Necessary	65.00 FL	*65.00 FL
13	1		*FRONT GRILLE	Cracked	692.00 FL	*692.00 FL
14	1		*FRONT GRILLE LOGO	Necessary	120.00 FL	*120.00 FL
15	1		*HEADLAMP RH	Cracked	2,579.00 FL	*2,579.00 FL
16	1		*HEADLAMP LOWER BRACKET RH	Not Necessary	185.00 FL	*- FL
17	1		*FRONT RH FENDER	Repair	1,030.00 FL	*- FL
18	1		*FRONT RH FENDER INNER SHIELD	Not Necessary	203.00 FL	*- FL
19	1		*HORN	Cracked	65.00 FL	*65.00 FL
20	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
21	1		*SET FRONT BUMPER UNDERCOVER CLIPS	Not Necessary	50.00 FS	*- FS
22	1		*SET FRONT GRILLE CLIPS	Necessary	30.00 FS	*20.00 FS
23	1		*SET FRONT RH FENDER INNER SHIELD CLIPS	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	9,427.00	7,634.00
- List Item Discount on L Items 10.00/10.00% (S\$)	926.70	758.40
Total Parts (S\$)	8,500.30	6,875.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,REMOVE AND REFIT PARTS	New	800.00	300.00
2	SPRAY PAINTING TO AFFECTED AREA	New	600.00	250.00
3	WIRING CHECK	New	50.00	30.00
4	TO REMOVE FRONT BUMPER SENSOR	New	100.00	60.00
5	TO PERFORM DIAGNOSTIC TEST	New	200.00	0.00
Gross Labour Cost (S\$)			1,750.00	640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >