



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN : TAN WAN CONG			Ref: CS3/ASM21000520/Gvf3e2 Date: 25/01/2021 Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SLQ 3664H	Veh. Inspected	SLK 9501L	
Policy No.		Coverage (\$)	0.00	
Claim No.	S1M030A4	Excess (\$)	0.00	
Assign From	TAN WAN CONG	Assign Date	12/01/2021	
2. Vehicle Particulars & Condition				
Make & Model	SEAT TOLEDO 1.4	c.c	1422	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	VSSZZZNHZH1012412	Colour	WHITE	
Odometer	240993 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	FIRENZA	6 mm	
L/H Front Tyre	205/55 R16	FIRENZA	6 mm	
R/H Rear Tyre	205/55 R16	FIRENZA	6 mm	
L/H Rear Tyre	205/55 R16	FIRENZA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5. General Information				
Accident Date	08/01/2021	Inspection Date	19/01/2021	
Survey held at	55 Serangoon North Ave 4, #02-10			
Repairer	1 STOP GARAGE PTE. LTD.			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		