

CS3/ AXA 21000520/Gvf3

ASSIGNMENT

Estimated Cost:

TP / WS / TP RES / OD RES / EVA / INV / MV

Inspect Vehicle No:

Workshop m/s

Insured:

Policy No.

Claims No

Insured:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Actual or Market Value:

DAC: Accident Report

SIA / PR Seen.

Est. Repairs

Sum Sum.

24 HRS

Date

Person Contacted

Vehicle IN / OUT

Date / Time

Action / Instruction

Date/Time File Pass to:

1)

Date/Time File Return to:

20/1/21-Typist

PRS

Days Of Repair: 5

Resurvey No. of Trip:

Addl Fees:

Site Insp: \$

Interview: \$

Photography: \$

Transportation: \$

Other: \$

Survey Fee:

Transportation:

Photography:

Interview:

Site Insp:

Other:

Vehicle No: SLK 950/L Reg: 07 Feb 2017

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Seat Toledo CC: 1422

Colour: white A/C: Insured / Std / NI / NA

Sp Reading: 240993 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: VSSZZZ NHZH 1012412

Gen Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FLR ENZA

Front: 6 mm R/Bal: 6 mm

L/Bal: 6 mm R/Bal: 6 mm

D.O.A: 8/1/2021 D.O.I: 19-01-21

Survey held at: W/S 3pm

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

