

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21000522/UVF3E2

Date: 01/02/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00045932000
Claimant Vehicle No: JNW890 Insured Vehicle No: SLZ5769D
Date of Loss: 08/01/2021 Nature of Claim: TP Claim No: SNM21D200135/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: JNW890
Make & Model: BMW 118, 1.6 (A) Engine No: 4B10HH1586
Reg. Date: 26/09/2012 (Man. Year: 2011) Chassis No: PL1CY3SNRBF006088
Colour: White Odometer: 140201 km
Engine Capacity: 1798 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18
Front Left Side: Viking 6 mm Rear Left Side: Viking 6 mm
Front Right Side: Viking 6 mm Rear Right Side: Viking 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,022.90	5,349.30	6,673.60	55.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,880.00	2,180.00	700.00	24.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,902.90	7,529.30	7,373.60	49.48
Approved Total (Overridden) (S\$)		6,000.00		
Nett Amount (S\$)	14,902.90	6,000.00	8,902.90	59.74

INSPECTION

Date of Assignment: 12/01/2021
Date Inspected: 12/01/2021 Inspected At: Ping Motor Pte Ltd (HQ)
1 Kaki Bukit Avenue 6, #01-25 Autobay @ Kaki Bukit
Singapore 417883
Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Feb 2021)
Parts:	144	BMW 118 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for JNW890)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Repair	693.00 FL	*- FL
2	2		*REAR BOOT LID HINGE L/R	Not Necessary	206.00 FL	*- FL
3	2		*REAR BOOT LID DAMPER L/R	Not Necessary	360.00 FL	*- FL
4	1		*REAR BOOT LID MECHANISM LOCK	Not Necessary	186.00 FL	*- FL
5	1		*REAR BOOT LID LOCK STRIKER	Not Necessary	55.00 FL	*- FL
6	1		*REAR BOOT LID INNER TRIM	Not Necessary	320.00 FL	*- FL
7	1		*REAR BOOT LID WEATHER STRIP	Twisted	165.00 FL	*165.00 FL
8	1		*REAR BOOT LID KEYLESS SMART	Not Necessary	142.00 FL	*- FL
9	2		*REAR BOOT LID REFLECTOR LAMP L/R	Not Necessary	620.00 FL	*- FL
10	1		*REAR BUMPER CENTRE BEAM	Bent	138.00 FL	*138.00 FL
11	1		*REAR BUMPER REINFORCEMENT BEAM	Bent	254.00 FL	*254.00 FL
12	2		*REAR BUMPER SIDE RETAINER L/R	Bent	64.00 FL	*64.00 FL
13	1		*REAR BUMPER SIDE REFLECTOR L/R	N/S Broken	136.00 FL	*68.00 FL
14	2		*REAR NO PLATE LAMP L/R	Not Necessary	90.00 FL	*- FL
15	1		*REAR NO PLATE LAMP BRACKET	Not Necessary	80.00 FL	*- FL
16	2		*REAR TAILLAMP L/R	Cracked	960.00 FL	*840.00 FL
17	1		*REAR END PANEL	Dented	689.00 FL	*486.00 FL
18	1		*REAR END PANEL INNER GARNISH	Twisted	241.00 FL	*241.00 FL
19	2		*REAR FENDER INNER SPONGES	Torn	1,016.00 FL	*610.00 FL
20	2		*REAR FENDER INNER SHIELD L/R	Tarnished	166.00 FL	*166.00 FL
21	1		*REAR SPARE TYRE PANEL	Repair	855.00 FL	*- FL
22	1		*REAR SPARE TYRE TOP BOARD	Torn	245.00 FL	*245.00 FL
23	1		*REAR BOOT LID STICKER	Not Necessary	30.00 FS	*- FS
24	1		*REAR BOOT LID INNER TRIM CLIP	Not Necessary	30.00 FS	*- FS
25	1		*REAR BUMPER ASSY SPORT	Distorted	1,800.00 FS	*1,080.00 FS
26	1		*REAR NO PLATE	Cracked	50.00 FS	*40.00 FS
27	1		*REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
28	1		*REAR BUMPER REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS
29	1		*REAR BUMPER REVERSE CAMERA	Not Necessary	280.00 FS	*- FS
30	1		*REAR END PANEL GARNISH CLIP	Not Necessary	30.00 FS	*- FS
31	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
32	2		*REAR FENDER INNER TRIM CLIP L/R	Not Necessary	60.00 FS	*- FS
33	1		*REAR EXHAUST SILENCER BOX	Bent / Twisted	2,400.00 FS	*1,000.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,791.00	5,677.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	768.10	327.70
Total Parts (\$\$)	12,022.90	5,349.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRINGS	New	80.00	30.00
2	TO REMOVE AND REPLACE AND REINSTALL REAR REVERSE SENSOR }	New	120.00	50.00
3	TO REMOVE AND REPLACE AND REINSTALL REAR REVERSE CAMERA }	New	100.00	0.00
4	TO REMOVE AND REINTALL REAR INTERIOR TRIMS, GARNISHES, SEATS, ETC. FOR NECESSARY REPAIR	New	160.00	80.00
5	TO REMOVE AND REPLACE EXHAUST PIPE	New	120.00	80.00
6	TO DISMANTLE, REPLACE FOR REAR BUMPER BODYKIT	New	150.00	0.00
7	TTO APPLY ANTI-RUSH UNDERCOAT	New	150.00	60.00
8	TO STRAIGHTEN, REPAIR, REALIGN ON REAR AFFECTED AREA AND REPLACE DAMAGED PARTS	New	1,000.00	900.00
9	TO SPRAY PAINTING ON AFFECTED AREA	New	1,000.00	980.00
Gross Labour Cost (\$)			2,880.00	2,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >