

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21000524/UPS3Q2

Date: 16/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800003704
Claimant
Vehicle No : SLC1260B **Insured Vehicle No :** SGV5001R
 Date of Loss: 09/01/2021 Nature of Claim: TP Claim No: 2316373350SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLC1260B**
 Make & Model: MAZDA 2, 1.5 SEDAN L SP.6EAT (A) Engine No: P520348514
 Reg. Date: 29/04/2016 (Man. Year: 2016) Chassis No: MM6DL2SAAGW196897
 Colour: Blue Odometer: 74845 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,657.00	1,678.80	6,978.20	80.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,280.00	1,450.00	2,830.00	66.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,937.00	3,128.80	9,808.20	75.82
Approved Total (Overridden) (S\$)		2,500.00		
Nett Amount (S\$)	12,937.00	2,500.00	10,437.00	80.68
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,907.45		
Global Sum Settlement (S\$)		2,900.00		

INSPECTION

Date of Assignment: 12/01/2021
 Date Inspected: 12/01/2021 Inspected At: Nineteen Autowerks Pte Ltd (HQ)
 BLK 15 KAKI BUKIT ROAD 4 #01-53
 BARTLEY BIZ CENTRE
 Singapore 417808
 Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Not Necessary	982.00 FL	*- FL
2	1		*BOOTLID LOGO	Not Necessary	128.00 FL	*- FL
3	1		*BOOTLID EMBLEM MAZDA 2	Not Necessary	115.50 FL	*- FL
4	1		*BOOTLID EMBLEM SKYACTIV	Not Necessary	116.00 FL	*- FL
5	2		*BOOTLID REFLECTOR	Not Necessary	784.00 FL	*- FL
6	1		*BOOTLID INNER TRIM	Not Necessary	214.50 FL	*- FL
7	1		*BOOTLID INNER LOCK	Not Necessary	286.40 FL	*- FL
8	1		*BOOTLID LOCK SWITCH	Not Necessary	117.80 FL	*- FL
9	1		*BOOTLID LOCK SENSOR	Not Necessary	168.70 FL	*- FL
10	1		*BOOTLID WEATHERSTRIP	Not Necessary	285.70 FL	*- FL
11	2		*REAR NUMBER PLATE LAMP	Not Necessary	144.00 FL	*- FL
12	1		*REAR BUMPER }	Dented / Deformed	896.00 FL	*896.00 FL
13	1		*REAR BUMPER LOWER }		376.00 FL	*- FL
14	2		*REAR BUMPER SIDE RETAINER	Not Necessary	256.60 FL	*- FL
15	2		*REAR BUMPER REFLECTOR	Not Necessary	129.40 FL	*- FL
16	1		*REAR BUMPER LOWER COVER	Not Necessary	127.00 FL	*- FL
17	1		*REAR END PANEL	Dented	829.00 FL	*600.50 FL
18	1		*REAR END PANEL TOP GARNISH	Twisted	227.00 FL	*227.00 FL
19	2		*TAILLAMP	Not Necessary	1,395.00 FL	*- FL
20	2		*TAILLAMP LOWER BRACKET	Not Necessary	188.40 FL	*- FL
21	2		*REAR FENDER INNER SHIELD	Not Necessary	304.00 FL	*- FL
22	2		*REAR FENDER INNER TRIM	Not Necessary	448.00 FL	*- FL
23	1		*EXHAUST PIPE ASSY	Not Necessary	896.00 FL	*- FL
24	1		*SUNDRIES	Not Necessary	60.00 FS	*- FS
25	1		*BOOTLID SEALANT	Not Necessary	100.00 FS	*- FS
26	2		*SET BOOTLID REFLECTOR CLIPS	Not Necessary	40.00 FS	*- FS
27	2		*BOOTLID REFLECTOR SEAL	Not Necessary	60.00 FS	*- FS
28	1		*SET BOOTLID INNER TRIM CLIPS	Not Necessary	35.00 FS	*- FS
29	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*50.00 FS
30	2		*SET TAILLAMP CLIP	Not Necessary	50.00 FS	*- FS
31	2		*TAILLAMP SEAL	Not Necessary	70.00 FS	*- FS
32	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
33	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*50.00 FS
34	2		*SET REAR FENDER INNER SHIELD CLIPS	Not Necessary	90.00 FS	*- FS
35	2		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	110.00 FS	*- FS
36	1		*SET REVERSE SENSOR C/W CONTROL MODULE	Shorted	300.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$) 10,540.00 2,023.50
- List Item Discount on L Items 20.00/20.00% (\$) 1,883.00 344.70

Total Parts (\$) 8,657.00 1,678.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING AND STRAIGHTEN PARTS ON ACCIDENT AREA	New	1,800.00	600.00
2	CHECK WIRING SYSTEM AFTER DISCONNECT AND CONNECT	New	80.00	20.00
3	R&R INTERIOR UPHOLTERY	New	200.00	80.00
4	R&R BOOTLID COMPONENT	New	100.00	0.00
5	R&R EXHAUST PIPE	New	300.00	0.00
6	R&R REVERSE SENSOR AND CHECK	New	100.00	50.00
7	TO APPLY UNDERCOATING FOR RUST PROOFING	New	200.00	0.00
8	SPRAY PAINTING ON ACCIDENT AREA	New	1,500.00	700.00
Gross Labour Cost (S\$)			4,280.00	1,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >