

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21000526/R1TF3N2**Date:** 08/12/2021**REFERENCE**

Insured/Claimant:	KOH CHEE HWEE JEFFERY	Policy No:	1800145592	
Date of Loss:	10/01/2021	Nature of Claim:	OD	Claim No: 5301667873SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG1822Y	Engine No:	CZE846849
Make & Model:	AUDI A3, 1.4 SEDAN TFSI (AMBIENTE) (A)	Chassis No:	WAUZZZ8V3K1008346
Reg. Date:	07/12/2018 (Man. Year: 2018)	Odometer:	43558 km
Colour:	Blue		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$97,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	41,564.00	24,711.20	16,852.80	40.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	28,112.00	18,057.00	10,055.00	35.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	69,676.00	42,768.20	26,907.80	38.62
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	69,376.00	42,468.20	26,907.80	38.79
+ GST 7.00/7.00% (S\$)	4,856.32	2,972.77	1,883.55	38.79
Nett Amount (S\$)	74,232.32	45,440.97	28,791.35	38.79

INSPECTION

Date of Assignment:	12/01/2021	
Date Inspected:	12/01/2021 Inspected At:	24 BENOI SECTOR SINGAPORE 629857 REPAIRER: PREMIUM AUTOMOBILES PTE LTD
Estimated Period of Repair:	21.0 days	

Adjuster: MOHD RASUL**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Torn	1,944.00 FS	*1,555.20 FS
2	1	*REAR BUMPER FIXING PARTS	Not Necessary	193.00 FS	*- FS
3	1	*WHEEL HOUSING LINER ADAPTER-LH/RH	N/s Cracked/O/s Not Necessary	76.00 FS	*29.84 FS
4	1	*REAR BUMPER GUIDE SECTION-LH/RH	N/s Missing/O/s Not Necessary	32.00 FS	*12.64 FS
5	2	*REAR BUMPER LOCKING MECHANISM	Serviceable	59.00 FS	*- FS
6	1	*REAR BUMPER SPOILER	Deformed	237.00 FS	*189.60 FS
7	1	*REAR LIGHT REFLECTOR-LH/RH	Ns Scratched/Os Not Necessary	82.00 FS	*32.56 FS
8	1	*LED TAIL LIGHT-LH OUTER	Scratched	877.00 FS	*701.60 FS
9	1	*TAIL LIGHT TRIM-LH OUTER	Serviceable	30.00 FS	*- FS
10	1	*LED TAIL LIGHT -LH INNER	Not Necessary	877.00 FS	*- FS
11	1	*TAIL LIGHT TRIM-LH INNER	Not Necessary	30.00 FS	*- FS
12	1	*REAR REINFORCEMENT BEAM	Serviceable	603.00 FS	*- FS
13	1	*REAR BUMPER BRACKET-LH	Cracked	27.00 FS	*21.44 FS
14	1	*REAR BUMPER BRACKET-RH	Cracked	29.00 FS	*22.48 FS
15	1	*REAR BUMPER GUIDE SECTION-LH	Cracked	67.00 FS	*52.96 FS
16	1	*REAR BUMPER GUIDE SECTION-RH	Serviceable	66.00 FS	*- FS
17	4	*REAR PARKING AID SENSOR-INNER/OUTER	Serviceable	968.00 FS	*- FS
18	4	*REAR PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
19	1	*REAR BUMPER WIRING SET	Serviceable	515.00 FS	*- FS
20	1	*VENT TRIM	Cracked	68.00 FS	*53.76 FS
21	1	*REAR FENDER-LH	Buckled	4,140.00 FS	*3,312.00 FS
22	1	*REAR WINDSCREEN	Necessary	814.00 FS	*651.20 FS
23	1	*1/4 GLASS-LH	Necessary	570.00 FS	*455.60 FS
24	1	*PRIMER	Necessary	20.00 FS	*15.76 FS
25	1	*BOTTOM PLATE-LH	Serviceable	187.00 FS	*- FS
26	1	*REAR INNER WHEEL HOUSING-LH	Repair	717.00 FS	*- FS
27	1	*REAR OUTER WHEEL HOUSING-LH	Bent	619.00 FS	*494.80 FS
28	1	*D-PILLAR REINFORCEMENT-LH	Serviceable	274.00 FS	*- FS
29	1	*D-PILLAR INNER SIDE PANEL-LH	Serviceable	1,071.00 FS	*- FS
30	1	*D-PILLAR PARTITION	Serviceable	19.00 FS	*- FS
31	1	*WHEEL HOUSING LINER-LH	Torn	240.00 FS	*191.60 FS
32	1	*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	89.00 FS	*- FS
33	1	*LUGGAGE COMPARTMENT TRIM-LH	Serviceable	771.00 FS	*- FS
34	1	*REAR ALUMINIUM RIM-LH	Scratched	1,166.00 FS	*932.80 FS
35	1	*SUPPORT FRAME	Serviceable	1,556.00 FS	*- FS
36	2	*TRACK ROD	Bent	202.00 FS	*80.80 FS
37	1	*COUPLING ROD	Bent	74.00 FS	*59.04 FS
38	1	*ANTI-ROLL BAR	Serviceable	244.00 FS	*- FS
39	1	*AXLE GUIDE-LH	Bent	301.00 FS	*240.80 FS
40	2	*WISHBONE-LOWER/UPPER	Bent	568.00 FS	*453.60 FS
41	1	*WHEEL BEARING HOUSING-LH-LH	Bent	663.00 FS	*530.40 FS
42	1	*WHEEL BEARING	Necessary	452.00 FS	*361.60 FS
43	1	*GAS SHOCK ABSORBER	Bent	249.00 FS	*199.20 FS
44	1	*LEVEL SENSOR-LH	Serviceable	587.00 FS	*- FS
45	2	*HEAD AIRBAG UNIT-LH/RH	Activated	3,726.00 FS	*2,980.80 FS
46	1	*SIDE AIRBAG UNIT-LH FRONT	Activated	1,520.00 FS	*1,216.00 FS
47	2	*AIRBAG CRASH SENSOR	Activated	389.00 FS	*622.40 FS
48	1	*AIRBAG CONTROL UNIT	Necessary	1,655.00 FS	*1,324.00 FS
49	1	*REAR WHEEL SPOILER-LH	Serviceable	35.00 FS	*- FS
50	2	*SEATBELT-LH/RH	Activated	2,206.00 FS	*1,764.80 FS
51	2	*SEATBELT HEIGHT ADJUSTER	Not Working	383.00 FS	*306.40 FS
52	1	*BACKREST COVER-LH	Torn	2,195.00 FS	*1,756.00 FS
53	1	*ROOF	Deformed	3,099.00 FS	*1,416.80 FS
54	1	*A-PILLAR TRIM-LH	Deformed	161.00 FS	*128.40 FS
55	1	*A-PILLAR TRIM-RH UPPER	Deformed	161.00 FS	*128.40 FS

Report was unsubmitted during this print-out.

12/8/21, 9:45 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	2		*B-PILLAR TRIM-LH/RH UPPER	Serviceable	434.00 FS	*- FS
57	2		*C-PILLAR TRIM-LH/RH UPPER	Serviceable	302.00 FS	*- FS
58	2		*D-PILLAR TRIM-LH/RH UPPER	Cracked	232.00 FS	*184.80 FS
59	2		*FRONT FOLDING GRAB HANDLE	Bent	283.00 FS	*226.40 FS
60	2		*REAR GRAB HANDLE-LH/RH	Bent	284.00 FS	*226.40 FS
61	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
62	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
63	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
64	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
65	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
66	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
67	1		*SUNDRIES	Necessary	400.00 FS	*194.24 FS
68	1		*B-PILLAR TRIM - LH LOWER	Cracked	116.00 FS	*92.80 FS
			Supplementary			
69	1		*BRAKE DICS REAR LHS	Bent	135.00 FS	*107.60 FS
			Supplementary			
70	1		*COVER FOR BEARING SUPPORT - LH	Scratched	6.00 FS	*4.64 FS
			Supplementary			
71	1		*BRAKE DISC COVER PLATE - LH	Bent	48.00 FS	*37.84 FS
			Supplementary			
72	1		*SPEED SENSOR - LH	Scratched	186.00 FS	*148.40 FS
			Supplementary			
73	1		*REAR BEARING SUPPORT BRACKET - LH	Broken	141.00 FS	*112.80 FS
			Supplementary			
F=Franchise part. S=SpcNett.						
Total Parts (S\$)						41,564.00 24,711.20
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND RENEW REAR PARKING AID.CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	280.00
2	TO RENEW REAR WINDSCREEN AND 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	600.00	600.00
3	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND 1/4 GLASS	New	400.00	0.00
4	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN	New	200.00	150.00
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS,BATTERY MANAGER,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO EQUIPMENT	New	1,400.00	1,400.00
6	TO REMOVE AND REINSTALL REAR SEAT,BACK REST,HAT TRAY,ABCD PILLAR TRIMS,LUGGAGE COMPARTMENT TRIMS,DISLODGE ROOF LINER AND DISENGAGE AIRBAG ETC	New	1,400.00	1,400.00
7	TO REMOVE AND RENEW LHS REAR WHEEL SUSPENSION WHEEL ASSY WITH SUBFRAME	New	2,400.00	2,400.00
8	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR O-LINER	New	800.00	0.00
9	TO PUT VEHICLE ON CAR O-LINER TO FACILITATE REPAIR	New	1,800.00	0.00
10	TO TOW BACK VEHICLE FROM ACCIDENT SCENE	New	280.00	0.00
11	TO REMOVE CENTRE CONSOLE,RENEW SEAT BELTS AND CONTROL UNIT,PILLAR TRIMS,ROOF LINING,BOTH CURTAIN AIR BAGS AND LHS FRONT BACKREST CUSHION AIRBAG	New	2,800.00	2,800.00
12	TO RENEW LHS FRONT SEAT BACKREST CUSHION ASSY	New	480.00	480.00
13	TO DISMANTLE AND RENEW REAR BUMPER.TO REPAIR RHS REAR FENDER.CUT OUT AND WELD LHS REAR FENDER,LHS INNER D-PILLAR PLATE-RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	8,400.00	4,500.00
14	TO RESPRAY REAR BUMPER,RHS REAR FENDER,LHS REAR FENDER,LHS INNER WHEEL HOUSING WITH CONNECTING PLATE,LHS INNER BOTTOM PLATE,LHS INNER D-PILLAR PLATES,LHS SILL PANEL,DOOR ENTRANCES,ROOF CHANNEL,DRAIN PANEL AND END PANELLING.TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS	New	6,400.00	3,575.00
15	TO RENEW LHS REAR RIM.TO CARRY OUT PRE AND POST WHEEL ALIGNMENT	New	280.00	280.00
16	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			28,112.00	18,057.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >