

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21000531/UEA3Q2**Date:** 19/07/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900015907
Claimant Vehicle No :	SMT7771C	Insured Vehicle No :	ES73E
Date of Loss:	09/01/2021	Nature of Claim:	TP
		Claim No:	4615415618SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMT7771C		
Make & Model:	MERCEDES-BENZ A200, 1.3 SALOON PROGRESSIVE (R18 LED) (A)	Engine No:	28291480297476
Reg. Date:	20/03/2020 (Man. Year: 2019)	Chassis No:	W1K1771872J177187
Colour:	White	Odometer:	8722 km
Engine Capacity:	1332 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Hankook 9 mm	Rear Left Side:	Hankook 9 mm
Front Right Side:	Hankook 9 mm	Rear Right Side:	Hankook 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,032.92	2,075.85	957.07	31.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,360.00	570.00	790.00	58.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,392.92	2,645.85	1,747.07	39.77
Approved Total (Overridden) (S\$)		2,100.00		
Nett Amount (S\$)	4,392.92	2,100.00	2,292.92	52.20
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,287.45		

INSPECTION

Date of Assignment:	12/01/2021	Quan De Motor Trading BLK 1 KAKI BUKIT AVENUE 6 #01-67 AUTOBAY SINGAPORE 417883 Singapore 417883
Date Inspected:	12/01/2021 Inspected At:	
Estimated Period of Repair:	2.0 days	

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented / Deformed	1,312.45 FN	*1,312.45 FN
2	1		*FRONT BUMPER CENTER LOWER GRILLE	Not Necessary	288.20 FN	*- FN
3	1		*FRONT BUMPER INNER CENTRE SUPPORT	Cracked	192.30 FN	*192.30 FN
4	1		*FRONT BUMPER SPONGE	Torn	105.00 FN	*105.00 FN
5	1		*FRONT BUMPER REINFORCEMENT	Dented	641.20 FN	*641.20 FN
6	1		*FRONT BUMPER PDC SENSOR	Serviceable	198.00 FN	*- FN
7	1		*FRONT SUPPORT PANEL	Repair	566.10 FN	*- FN
8	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	3,363.25	2,300.95
- Nett Item Discount on N Items 10.00/10.00% (S\$)	330.33	225.10
Total Parts (S\$)	3,032.92	2,075.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING }	New	60.00	40.00
2	TO REMOVE & REFIX FRONT PDC SENSOR }	New	100.00	0.00
3	TO RESET & REPROGRAMME CLEAR FAULT CODE	New	200.00	80.00
4	LABOUR FOR PANEL BEATING ,WELDING & RENEW PARTS	New	500.00	250.00
5	SPRAY PAINTING	New	500.00	200.00
Gross Labour Cost (\$)			1,360.00	570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >