

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21000532/T1QD3E2

Date: 01/07/2021

REFERENCE

Insured/Claimant:	AMINUR BIN RASID	Policy No:	1900093761		
Date of Loss:	08/01/2021	Nature of Claim:	OD	Claim No:	0803281614SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ635P	Engine No:	A728J160N16B16A
Make & Model:	MINI COOPER, 1.6 (A)	Chassis No:	WMWZB32000WL92441
Reg. Date:	03/05/2012 (Man. Year: 2012)	Odometer:	157411 km
Colour:	Grey		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	S\$34,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,711.40	7,596.06	16,115.34	67.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,900.00	1,570.00	1,330.00	45.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,611.40	9,166.06	17,445.34	65.56
Approved Total (Overridden) (S\$)		7,300.00		
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	26,011.40	6,700.00	19,311.40	74.24
+ GST 7.00/7.00% (S\$)	1,820.80	469.00	1,351.80	74.24
Nett Amount (S\$)	27,832.20	7,169.00	20,663.20	74.24

INSPECTION

Date of Assignment:	12/01/2021	
Date Inspected:	12/01/2021 Inspected At:	Alpha Car Services Pte Ltd (HQ) Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit Autobay Singapore 417883
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	1,668.00 FL	*1,668.00 FL
2	1		*BONNET LOCK	Not Necessary	187.00 FL	*- FL
3	2		*BONNET HINGE	Repair	286.00 FL	*- FL
4	2		*BONNET ABSORBER	Repair	736.00 FL	*- FL
5	1		*BONNET LOCK SENSOR	Not Necessary	269.00 FL	*- FL
6	2		*FRONT FENDER	Not Necessary	2,990.00 FL	*- FL
7	2		*FRONT FENDER COWLING	Not Necessary	494.00 FL	*- FL
8	2		*FRONT FENDER ARCH GARNISH	Not Necessary	786.00 FL	*- FL
9	2		*HEADLAMP ASSY	Cracked	7,472.00 FL	*1,773.50 FL
10	2		*HEADLAMP BRACKET	Not Necessary	210.00 FL	*- FL
11	2		*HEADLAMP MOUNT PANEL	Repair	914.00 FL	*- FL
12	1		*BONNET HEADLAMP CHROME TRIM	O/S NotNecessary / N/S Cut	596.00 FL	*298.00 FL
13	1		*FRONT BUMPER	Cracked	1,399.00 FL	*729.03 FL
14	2		*FRONT BUMPER FOGLAMP	Not Necessary	774.00 FL	*- FL
15	1		*FRONT BUMPER AIR INTAKE DUCT	Cracked	286.00 FL	*286.00 FL
16	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	178.00 FL	*- FL
17	1		*FRONT BUMPER LOWER SPOILER	Not Necessary	1,190.00 FL	*- FL
18	1		*RADIATOR GRILLE	Cracked	678.00 FL	*283.32 FL
19	3		*RADIATOR GRILLE BRACKET	Not Necessary	501.00 FL	*- FL
20	1		*BONNET MINI EMBLEM	Necessary	117.00 FL	*117.00 FL
21	1		*FRONT BUMPER LOWER GRILLE	Distorted	295.00 FL	*295.00 FL
22	1		*FRONT BUMPER LOWER GRILLE SILVER TRIM	Cracked	177.00 FL	*177.00 FL
23	2		*FRONT BUMPER FOGLAMP INNER BRACKET	Not Necessary	338.00 FL	*- FL
24	1		*FRONT BUMPER TOW CAP	Not Necessary	73.00 FL	*- FL
25	1		*FRONT BUMPER SPONGE	Cracked	187.00 FL	*187.00 FL
26	1		*FRONT BUMPER REINFORCEMENT	Bent	557.00 FL	*557.00 FL
27	1		*FRONT SUPPORT PANEL	Bent	675.00 FL	*675.00 FL
28	1		*FRONT SUPPORT PANEL TOP GARNISH	Cracked	389.00 FL	*389.00 FL
29	1		*ENGINE UNDER COWLING	Not Necessary	371.00 FL	*- FL
30	1		*BONNET CHROME TRIM	Deformed	299.00 FL	*299.00 FL
31	2		*FRONT FENDER CHROME MOULDING	Cut	534.00 FL	*534.00 FL
32	8		*BONNET INSULATOR CLIPS	Not Necessary	44.00 FS	*- FS
33	3		*BONNET WEATHERSTRIP	Not Necessary	144.00 FS	*- FS
34	16		*FRONT FENDER COWLING CLIPS	Not Necessary	88.00 FS	*- FS
35	12		*FRONT FENDER ARCH GARNISH CLIPS	Not Necessary	66.00 FS	*- FS
36	10		*FRONT BUMPER CLIPS	Necessary	55.00 FS	*30.00 FS
37	1		*FRONT SUPPORT PANEL TOP GARNISH CLIPS (6PCS)	Necessary	33.00 FS	*10.00 FS
38	6		*ENGINE UNDER COWLING CLIPS	Not Necessary	33.00 FS	*- FS
39	1		*FRONT LICENCE PLATE AND FRAME	Bent	55.00 FS	*55.00 FS
40	1		*RADIATOR COOLANT	Necessary	80.00 FS	*60.00 FS
41	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	26,274.00	8,422.85
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,562.60	826.79
Total Parts (\$\$)	23,711.40	7,596.06

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE / RENEW ACCIDENT DAMAGED PORTIONS. TO PANEL BEAT, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS	New	1,200.00	700.00
2	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS INCLUDING FOCUSING HEADLAMPS	New	200.00	40.00
3	TO REMOVE AND REFIT RADIATOR TO FACILITATE REPAIR. TO PERFORM PRESSURE TEST AND CHECK COOLING SYSTEM FUNCTIONALITY	New	200.00	100.00
4	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA / PANEL	New	1,200.00	700.00
5	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR	New	100.00	30.00
Gross Labour Cost (\$\$)			2,900.00	1,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >