

ASS. REC. BY:

Taufikh

REF:

CS/ AIG 21000532 / T, 9, 93.

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No. 1900093761

Claims No. 0803281614SG

Sum Insured: Excess: 600

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

| | |
|-----|-----|
| N/S | O/S |
| | |

Bal. or Market Value:

934K.

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SLZ 63SP

Yr Regn:

2012 / May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mini Cooper Countryman c.c 1598

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading:

157411

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WMWZB32000W29241

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / STD A/Rim or

Tyre Size:

F: 225/50R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Fallen

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

D.O.I.

12/1/21

Survey held at

Alpha Car

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

13/01/21 @ 4.43pm revert to AIG via Merimen.

14/01/21 @ 9.23am Kok Chong informed C/A not more than \$11K via Merimen.

14/01/21 @ 9.41am Informed wksp C/A not more than \$11K or whichever lower.

Taufikh finalised with Cailing LS \$7300, 6 days (Red \$19311.40, 73%)

Date/Time, File Pass to?

☐

Preli. Report

☐

Final Report

1) 18/06 Typist

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Report Format: MER-OD

Lump Sum: 7300

Alpha Car Services Pte Ltd

Blk C Kaki Bukit Ave 6 #01-59 Autobay@Kakit Bukit Singapore 417883

Office: (65) 6509 8258

Make/Model: MINI COOPER COUNTRYMAN 1.6 AT

Engine/Chassis No.: WMWZB32000WL92441


Date of accident: 08/01/2021

Damaged area: Front

Date: 11/01/2021

Claim Type: OD

VRN: SLZ 635P



| List items | | | | |
|---------------|---------------------------------------|-----|-------------|-------------|
| S/N | Parts description | QTY | UNIT PRICE | AMOUNT |
| 1 | Bonnet | 1 | \$ 1,668.00 | \$ 1,668.00 |
| 2 | Bonnet lock | 1 | \$ 187.00 | \$ 187.00 |
| 3 | Bonnet hinge | 2 | \$ 143.00 | \$ 286.00 |
| 4 | Bonnet absorber | 2 | \$ 368.00 | \$ 736.00 |
| 5 | Bonnet lock sensor | 1 | \$ 269.00 | \$ 269.00 |
| 6 | Front fender | 2 | \$ 1,495.00 | \$ 2,990.00 |
| 7 | Front fender cowl | 2 | \$ 247.00 | \$ 494.00 |
| 8 | Front fender arch garnish | 2 | \$ 393.00 | \$ 786.00 |
| 9 | Headlamp assy | 2 | \$ 3,736.00 | \$ 7,472.00 |
| 10 | Headlamp bracket | 2 | \$ 105.00 | \$ 210.00 |
| 11 | Headlamp mount panel | 2 | \$ 457.00 | \$ 914.00 |
| 12 | Bonnet headlamp chrome trim | 2 | \$ 298.00 | \$ 596.00 |
| 13 | Front bumper | 1 | \$ 1,399.00 | \$ 1,399.00 |
| 14 | Front bumper foglamp | 2 | \$ 387.00 | \$ 774.00 |
| 15 | Front bumper air intake duct | 1 | \$ 286.00 | \$ 286.00 |
| 16 | Front bumper side retainer | 2 | \$ 89.00 | \$ 178.00 |
| 17 | Front bumper lower spoiler | 1 | \$ 1,190.00 | \$ 1,190.00 |
| 18 | Radiator grille | 1 | \$ 678.00 | \$ 678.00 |
| 19 | Radiator grille bracket | 3 | \$ 167.00 | \$ 501.00 |
| 20 | Bonnet "MINI" emblem | 1 | \$ 117.00 | \$ 117.00 |
| 21 | Front bumper lower grille | 1 | \$ 295.00 | \$ 295.00 |
| 22 | Front bumper lower grille silver trim | 1 | \$ 177.00 | \$ 177.00 |
| 23 | Front bumper foglamp inner bracket | 2 | \$ 169.00 | \$ 338.00 |
| 24 | Front bumper tow cap | 1 | \$ 73.00 | \$ 73.00 |
| 25 | Front bumper sponge | 1 | \$ 187.00 | \$ 187.00 |
| 26 | Front bumper reinforcement | 1 | \$ 557.00 | \$ 557.00 |
| 27 | Front support panel | 1 | \$ 675.00 | \$ 675.00 |
| 28 | Front support panel top garnish | 1 | \$ 389.00 | \$ 389.00 |
| 29 | Engine under cowl | 1 | \$ 371.00 | \$ 371.00 |
| 30 | Bonnet chrome trim | 1 | \$ 299.00 | \$ 299.00 |
| 31 | Front fender chrome moulding | 2 | \$ 267.00 | \$ 534.00 |
| Subtotal | | | \$ | 25,626.00 |
| List discount | | | | 10.00% |
| Total | | | \$ | 23,063.40 |

Repair Estimate

| Special nett items | | | | |
|--------------------|---------------------------------------|-----|------------|-----------|
| No. | Parts description | QTY | UNIT PRICE | AMOUNT |
| 1 | Bonnet insulator clips | 8 | \$ 5.50 | \$ 44.00 |
| 2 | Bonnet weatherstrip | 3 | \$ 48.00 | \$ 144.00 |
| 3 | Front fender cowling clips | 16 | \$ 5.50 | \$ 88.00 |
| 4 | Front fender arch garnish clips | 12 | \$ 5.50 | \$ 66.00 |
| 5 | Front bumper clips | 10 | \$ 5.50 | \$ 55.00 |
| 6 | Front support panel top garnish clips | 6 | \$ 5.50 | \$ 33.00 |
| 7 | Engine under cowling clips | 6 | \$ 5.50 | \$ 33.00 |
| 8 | Front licence plate and frame | 1 | \$ 55.00 | \$ 55.00 |
| 9 | Radiator coolant | 1 | \$ 80.00 | \$ 80.00 |
| 10 | Sundries | 1 | \$ 50.00 | \$ 50.00 |
| Total | | | | \$ 648.00 |

X
X
X
X
3000—
1000—
X
61—
?
X

| Labour | | | |
|----------------------|--|-----------|--------------|
| No. | Description | Work unit | Amount |
| 1 | To dismantle / renew accident damaged portions. To panel beat, reshape, straighten, orientate and align repair / replacement parts. | 6 | \$ 1,200.00 |
| 2 | To disconnect front wire harness of electrical components to facilitate repairs, reconnect and check functions including focusing headlamps. | 1 | \$ 200.00 |
| 3 | To remove and refit radiator to facilitate repair. To perform pressure test and check cooling system functionality. | 1 | \$ 200.00 |
| 4 | Supply spray paint material and necessary items to respray affected area / panel. | 6 | \$ 1,200.00 |
| 5 | To rust proof all affected portions after repair. | 0.5 | \$ 100.00 |
| Total labour | | | \$ 2,900.00 |
| Estimate Grand Total | | | \$ 26,611.40 |

700
40.
100? photo.
700
30.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before and after spray painting
- To display damaged portions during resurvey
- Parts price to be confirmed
- Third party's to be on "Without Prejudice" basis
- No time limit for claims allowed
- Supply of materials must be resurveyed and is subject to approval from Insurance Company

Agreed with the Repairer
Signed by
Date

Tanpin 97495749 / 67418437
Ex: +64
Not Authorise. 06days
12/1/21 e 1615
Lumpsum
Resurvey after repair